


CERTIFICATE NUMBER
**Commercial Vehicle Inspection Certificate
Traffic Safety Act**
**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	MARK CROUCH BACKHOE SERVICE LTD		
Address:	RR#2 SITE 9 COMP 15		
City:	SUNDRE	Province:	AB
Postal Code:	T0M1X0		
Telephone Number:	(403) 638-2649		
Vehicle Identification Number:	2SFNM7699L1046397		
Make:	Renn	Model:	Tridem
Year:	2020	Unit Number:	MCT43
Odometer:	KM	Licence Plate Number:	5VV252
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE
PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Lucky 13 Heavy Duty Repair Ltd.	18700
Inspection Technician Name:	Technician Number:
Lucas Amos	D3547
Inspection Technician Signature:	
Inspection Date:	2025/10/15