



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE GWNER AND VEHICLE IDENTIFICATION

Vehicle Typ	pe:	Trailer		Seatir	ng Capa	city:		4	100		
GVW:		kg		Brake	Type:		Air				
Owner Name:		CYKO 77 LTD									
Address:	521	138 RANGE ROAD 215									
City:	SHE	ERWOOD	PARK	Province:	AB			Posta	I Code:	T8E	1B3
Telephone Number:			(780) 220-8934								
Vehicle Ide	ntific	ation Nu	mber:	1TKB047	279M07	7549					
Make:	1	Trail King				Model:	Tanden	n			
Year:	2	2009				Unit Nu	ımber:		T20A		
Odometer:	1	167092 K	M Li	cence Plate N	lumber:	5VN	1983		Provinc	e:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:			
MKS Trailer & Equipment Repairs Ltd. 13232				
Inspection Technician Name	:	Technician Number:		
Michael Orkusz	A4298			
Inspection Technician Signa	iture:	Mik Cary		
Inspection Date:	2025/09/22			