B48-1





CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

| Vehicle Type: | | Truck | | Seating Capacity: | | ity: | | | | |
|--------------------------------|--------------------|----------------------|-----------------------------|-------------------|-----------------|--------|----------|------------|----|-----|
| GVW: | | 24500 kg | | Brake Type: | | Air | Air | | | |
| Owner Name: | | G H K TYRANSPORT LTD | | | | | | | | |
| Address: | 2121 53 ST SW | | | | | | | | | |
| City: | EDMONTON | | | Province: AB | | | Postal C | stal Code: | | 1X3 |
| Telephone | Num | ber: (7 | 80) 902-981 | 8 | | | | | | |
| Vehicle Identification Number: | | | er: | 1HTGGAET1XH593904 | | | | | | |
| Make: | ake: International | | | N | Model: S Series | | | | | |
| Year: | 1999 | | | ι | Unit Number: | | | | | |
| Odometer: | 3 | 80806 KM | 806 KM Licence Plate Number | | umber: | 89P303 | | ovince | e: | AB |

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

| Inspection Facility Name: | | Facility Number: | | | |
|------------------------------|------------|--------------------|--|--|--|
| Fast Tire & Repair Service I | td. | 21106 | | | |
| Inspection Technician Nam | e: | Technician Number: | | | |
| Anit Kumar | | B1920 | | | |
| Inspection Technician Sign | ature: | | | | |
| Inspection Date: | 2025/05/20 | SH | | | |