G10-1





CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Typ	e:	Truck			Seating Capacity:		:					
GVW:		kg			Brake Type:			Hydraulic				
Owner Nam	ne:	RECYC	LE WEST	INC								
Address:	6 S/	ABRINA	WAY									
City:	HEA	DINLEY		Province: AB Po		Posta	stal Code: F		10A7			
Telephone	Num	ber:	(000) 000-	0000		-						
Vehicle Ide	ntific	ation Nu	mber:	21	NP2HM7	XOKM	2557	73				
Make: PETERBUILT					Model: 337							
Year:	2	019					Unit	t Number:		3004		
Odometer:	6	33251 K	М	Licence	Plate Nu	ımber:		CHM991		Provinc	e:	МВ

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:		Facility Number: 20091				
Kelly Kutzner						
Inspection Technician Nam	e:	Technician Number:				
Joshua Rumble		B6584				
Inspection Technician Sign	ature:	I SPI Am				
Inspection Date:	2024/12/21	0001/90				