

Inspection Facility Name:



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Truck				Seating Capacity:			<i>ı</i> :					
GVW:		46500 kg				Brake			Air					
Owner Nam	ne:	LOADSTAR DISPATCHERS												
Address: 7823 34TH STREET														
City:	EDMONTON				Province: AB				Post			al Code:	T6B2V5	
Telephone Number: (780) 466-1188														
Vehicle Identification Number:					5KJJAEAV19PAH6437									
Make: Western Star							Мо	del:	Conventional					
Year: 2		2009					Unit Nur			mber:		8917		
Odometer:		632813 KM		Lice	icence Plate Number			:	0CB003			Province	e:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

Facility Number:

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Loadstar Dispatchers (1963	10459				
Inspection Technician Nam	Technician Number:				
Bill Dau	A2706				
Inspection Technician Sign	ature: Bill Dan				
Inspection Date:	2024/12/19				