



**CERTIFICATE NUMBER**

**Commercial Vehicle Inspection Certificate  
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE  
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	24500 kg	Brake Type:	Air
Owner Name:	GHK TRANSPORT LTD		
Address:	2121 53ST NW		
City:	EDMONTON	Province:	AB
		Postal Code:	T6X1X3
Telephone Number:	(780) 902-9818		
Vehicle Identification Number:	1FVJALCK34DN43247		
Make:	Freightliner	Model:	Conventional
Year:	2004	Unit Number:	
Odometer:	6553482 KM	Licence Plate Number:	62P354
		Province:	AB

**IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE**

**PART 2 - CERTIFICATION**

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Fast Tire & Repair Service Ltd.	21106
Inspection Technician Name:	Technician Number:
Anit Kumar	B1920
Inspection Technician Signature:	
Inspection Date:	2025/04/21