

Alberta Government

CV8538157



8008700008538157

CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**


**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:		
GVW:	63500 kg	Brake Type:	Air	
Owner Name:	TRANS TECH LTD			
Address:	PO BOX 421			
City:	PLAMONDON	Province:	AB	Postal Code:
Telephone Number:	(780) 404-1355			
Vehicle Identification Number:	1XKDP4EX6GR983755			
Make:	Kenworth	Model:	Construct	
Year:	2016	Unit Number:		
Odometer:	858017 KM	Licence Plate Number:	L04588	Province:
				AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Northern Heavy Duty Repair Ltd.	21386
Inspection Technician Name:	Technician Number:
Bradley Benluk	B9515
Inspection Technician Signature:	
Inspection Date:	2025/05/08