


Unit # 11 Truck

Vol-3



CV8591549



80087200008591549

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate  
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	30800 kg	Brake Type:	Air
Owner Name:	LESAK VAC & WATER HAULING LTD		
Address:	6208 52 STREET		
City:	TABER	Province:	AB
		Postal Code:	T1G 1J7
Telephone Number:	(403) 223-3430		
Vehicle Identification Number:	1NKDX4TX6ER967999		
Make:	Kenworth	Model:	Construct
Year:	2014	Unit Number:	11
Odometer:	161018 KM	Licence Plate Number:	K21987
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Oilfield Solutions Ltd	21211
Inspection Technician Name:	Technician Number:
Thomas Johnson	D1793
Inspection Technician Signature:	
Inspection Date:	2026/02/25