



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	LAURLEE ENERGY SERVICES LTD		
Address:	PO BOX 1095		
City:	NISKU	Province:	AB
		Postal Code:	T9E8A8
Telephone Number:	(250) 319-8868		
Vehicle Identification Number:	2M5131524E1139991		
Make:	MANAC	Model:	Trombone
Year:	2014	Unit Number:	TB304
Odometer:	KM	Licence Plate Number:	5ZM639
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
SKS Logistics Ltd	20130
Inspection Technician Name:	Technician Number:
Christopher Boersma	C6488
Inspection Technician Signature:	
Inspection Date:	2025/07/22

