


X02-1



CV8573409



80087100008573409

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	MAGOLA TRANS INC		
Address:	153 370 5222-130 AVE SE		
City:	CALGARY	Province:	AB
		Postal Code:	T2Z0G4
Telephone Number:	403		
Vehicle Identification Number:	1FUJA6CK17LX57458		
Make:	Freightliner	Model:	Tractor
Year:	2007	Unit Number:	
Odometer:	3042008 KM	Licence Plate Number:	
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	G.G.S Truck Repairs Ltd.	Facility Number:	17060
Inspection Technician Name:	Arvinder Singh	Technician Number:	D2744
Inspection Technician Signature:			
Inspection Date:	2025/10/25		