



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

~~1108-1~~

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

| | | | |
|--------------------------------|---------------------|-----------------------|------------|
| Vehicle Type: | Truck | Seating Capacity: | |
| GVW: | 46500 kg | Brake Type: | Air |
| Owner Name: | 1215087 ALBERTA LTD | | |
| Address: | 4735 154 AVE NW | | |
| City: | Edmonton | Province: | AB |
| | | Postal Code: | T5Y 0C2 |
| Telephone Number: | (780) 937-6303 | | |
| Vehicle Identification Number: | 3HSCNAPR44N092775 | | |
| Make: | International | Model: | Eagle 9400 |
| Year: | 2004 | Unit Number: | 125 |
| Odometer: | 125889 KM | Licence Plate Number: | 0EC379 |
| | | Province: | AB |

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

| | | | |
|----------------------------------|----------------------------------|--------------------|-------|
| Inspection Facility Name: | BRV Truck & Trailer Repairs Ltd. | Facility Number: | 20375 |
| Inspection Technician Name: | Balwinder Natt | Technician Number: | C8422 |
| Inspection Technician Signature: | | | |
| Inspection Date: | 2025/08/01 | | |

~~1108-1~~