



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	63500 kg	Brake Type:	Air
Owner Name:	SAN FORESTRY LTD.		
Address:	BOX 480		
City:	PLAMONDON	Province:	AB
		Postal Code:	T0A2T0
Telephone Number:	(780) 798-3447		
Vehicle Identification Number:	1XKZDP0X2NJ990463		
Make:	Kenworth	Model:	Construct
Year:	2022	Unit Number:	SL30
Odometer:	359134 KM	Licence Plate Number:	A00647
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Avenir Mechanical Ltd.	19495
Inspection Technician Name:	Technician Number:
Cody Plamondon	C2242
Inspection Technician Signature:	
Inspection Date:	2025/07/09

Retorque wheels.