



**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	10000 kg	Brake Type:	Hydraulic
Owner Name:	XLT Transport Ltd		
Address:	23011 110 Ave		
City:	Edmonton	Province:	AB
		Postal Code:	T6S 1Y2
Telephone Number:	(780) 446-4603		
Vehicle Identification Number:	2AYNFBJT2H3513797		
Make:	Hino	Model:	Hino 338
Year:	2017	Unit Number:	167
Odometer:	271028 KM	Licence Plate Number:	A53771
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Performance Heavy Duty Ltd	21855
Inspection Technician Name:	Technician Number:
Hendrik Van Engelen	D3531
Inspection Technician Signature:	
Inspection Date:	2026/04/09