



E19+

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	BARRY AND LESLIE DAVIS		
Address:	BOX 735		
City:	KIRRIEMUIR	Province:	AB
		Postal Code:	T0C1R0
Telephone Number:	(403) 596-5170		
Vehicle Identification Number:	3HSDZAPR8KN392213		
Make:	INTERNATIONAL	Model:	LT625
Year:	2019	Unit Number:	
Odometer:	687462 KM	Licence Plate Number:	
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Industrial Diesel Repair And Performance Ltd	Facility Number:	20148
Inspection Technician Name:	Sebastian Voswinkel	Technician Number:	B9223
Inspection Technician Signature:			
Inspection Date:	2026/01/20		