

D26-4



CV8519136



80087700008519136

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	54300 kg	Brake Type:	Air
Owner Name:	JRF OILFIELD SERVICES LTD		
Address:	BOX 7382		
City:	Edson	Province:	AB
		Postal Code:	T7E1V6
Telephone Number:	(780) 517-8740		
Vehicle Identification Number:	1NPTP4EX8KD633596		
Make:	Peterbilt	Model:	Conventional
Year:	2019	Unit Number:	52
Odometer:	511895 KM	Licence Plate Number:	0FA125
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	JRF Oilfield Services Ltd.	Facility Number:	20459
Inspection Technician Name:	Raphie Laurente	Technician Number:	D2934
Inspection Technician Signature:			
Inspection Date:	2025/11/22		