

K29-3



CV8361448



80087500008361448

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	49000 kg	Brake Type:	Air
Owner Name:	REMUDA STEEL CORP		
Address:	602 2ND ST NW		
City:	THREE HILLS	Province:	AB
		Postal Code:	T0M-2A0
Telephone Number:	(403) 607-1213		
Vehicle Identification Number:	3AKJGLD56GSGP2399		
Make:	Freightliner	Model:	Cascadia
Year:	2016	Unit Number:	01
Odometer:	1529431 KM	Licence Plate Number:	U23567
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
742045 Alberta Ltd.	19887
Inspection Technician Name:	Technician Number:
Michael Lorentzen	A0526
Inspection Technician Signature:	
Inspection Date:	2025/12/30

Remuda Office Copy