



**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

| | | | |
|---------------------------------------|--------------------------------|------------------------------|---------|
| Vehicle Type: | Trailer | Seating Capacity: | |
| GVW: | kg | Brake Type: | Air |
| Owner Name: | Jonny's Light Oilfield Hauling | | |
| Address: | Box 214, 2420 Sparrow Drive | | |
| City: | Nisku | Province: | AB |
| | | Postal Code: | T9E8A2 |
| Telephone Number: | (780) 913-9959 | | |
| Vehicle Identification Number: | 2E9D20B2263003820 | | |
| Make: | Scona | Model: | booster |
| Year: | 2006 | Unit Number: | B9 |
| Odometer: | 2361 KM | Licence Plate Number: | 6DS488 |
| | | Province: | AB |

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

| | |
|---|---------------------------|
| Inspection Facility Name: | Facility Number: |
| Jonny's Light Oilfield Hauling Ltd. | 16612 |
| Inspection Technician Name: | Technician Number: |
| Tyler Winters | D2352 |
| Inspection Technician Signature: | <i>Tyler Winters</i> |
| Inspection Date: | 2026/02/17 |