

N03-3



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate  
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	49000 kg	Brake Type:	Air
Owner Name:	LYNDEN TRANSPORT INC		
Address:	27340 ACHESON ROAD		
City:	ACHESON	Province:	AB
		Postal Code:	T7X 6B1
Telephone Number:	(780) 999-8683		
Vehicle Identification Number:	3AKJHPDV1KSKG6875		
Make:	Freightliner	Model:	CASCADIA 116
Year:	2019	Unit Number:	1152
Odometer:	1084340 KM	Licence Plate Number:	E89153
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Canadian Lynden Transport Co.	Facility Number:	13412
Inspection Technician Name:	Christopher Nemlander	Technician Number:	C2550
Inspection Technician Signature:	<i>Chris Nemlander</i>		
Inspection Date:	2025/10/15		