



**Commercial Vehicle Inspection Certificate  
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	63500 kg	Brake Type:	Air
Owner Name:	Site Resource Group GP Corporation		
Address:	Box 210		
City:	Cold Lake	Province:	AB
		Postal Code:	T9M1P1
Telephone Number:	(780) 826-0369		
Vehicle Identification Number:	1XKDD40X7ER969229		
Make:	Kenworth	Model:	Construct
Year:	2014	Unit Number:	12-060
Odometer:	714632 KM	Licence Plate Number:	CWJ0804
		Province:	AB

**IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE**

**PART 2 - CERTIFICATION**

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Site Resource Group GP Corporation	21951
Inspection Technician Name:	Technician Number:
Jasen Reaume	C4695
Inspection Technician Signature:	
Inspection Date:	2026/01/09