



**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	MAGOLA OLGA		
Address:	1711-135 Lynnview Rd SE		
City:	Calgary	Province:	AB
		Postal Code:	T2C2G6
Telephone Number:	403		
Vehicle Identification Number:	4V4NC9EH0LN241889		
Make:	Volvo	Model:	VNL760
Year:	2020	Unit Number:	889
Odometer:	911827 KM	Licence Plate Number:	
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	G.G.S Truck Repairs Ltd.	Facility Number:	17060
Inspection Technician Name:	Ravinder Dhaliwal	Technician Number:	D3439
Inspection Technician Signature:			
Inspection Date:	2025/12/07		