

T27-1



CV8721506



80087500008721506

CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Northwest Harvesting 2.0		
Address:	PO Box 117		
City:	Slave Lake	Province:	AB
		Postal Code:	T0G 2A0
Telephone Number:	(780) 849-5578		
Vehicle Identification Number:	2E9L50F3613003186		
Make:	Scona	Model:	Tri Axle
Year:	2001	Unit Number:	LB01
Odometer:	KM	Licence Plate Number:	6RN990
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
2537984 AB Ltd	22251
Inspection Technician Name:	Technician Number:
Ryan Wieler	C5377
Inspection Technician Signature:	
Inspection Date:	2026/06/17