



80087500008499506

CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate  
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	14700 kg	Brake Type:	Hydraulic
Owner Name:	Natural Resource Recovery Group (2012) Inc		
Address:	22504 113 Ave Nw		
City:	Edmonton	Province:	AB
		Postal Code:	T5S2S5
Telephone Number:	(780) 452-2321		
Vehicle Identification Number:	2AYNF8JV3J3S13797		
Make:	Hino	Model:	Hino
Year:	2018	Unit Number:	8002
Odometer:	626186 KM	Licence Plate Number:	A23451
		Province:	AB

**IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE**

**PART 2 - CERTIFICATION**

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	I & S Truck and Trailer Inc.	Facility Number:	13947
Inspection Technician Name:	John Badger	Technician Number:	66882
Inspection Technician Signature:			
Inspection Date:	2026/02/05		