


R01-287



CV8621218



80087800008621218

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	63500 kg	Brake Type:	Air
Owner Name:	KENCOR HEAVY HAUL LTD		
Address:	1202 16 AVE		
City:	NISKU	Province:	AB
Postal Code:	T9E0A9		
Telephone Number:	(780) 729-7938		
Vehicle Identification Number:	3AKJHHDR9NSND1569		
Make:	Freightliner	Model:	Cascadia
Year:	2022	Unit Number:	329
Odometer:	556729 KM	Licence Plate Number:	A92067
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
D-Town Diesel Repair Ltd.	21763
Inspection Technician Name:	Technician Number:
Gagandeep Singh	D2462
Inspection Technician Signature:	
Inspection Date:	2026/01/20