



**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	GN MOTORS LTD		
Address:	6520 174 AVE NW		
City:	EDMONTON	Province:	AB
		Postal Code:	T5Y3R2
Telephone Number:	(780) 993-8081		
Vehicle Identification Number:	2D9DS4C485L017675		
Make:	Decap	Model:	38ft Tri/A
Year:	2005	Unit Number:	
Odometer:	KM	Licence Plate Number:	6SH626
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
North Truck and Trailer Repair Ltd.	19938
Inspection Technician Name:	Technician Number:
Daljeet Dhillon	D1976
Inspection Technician Signature:	
Inspection Date:	2026/05/09



COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle		Gross Vehicle Weight registered	
Trailer		kg	
Vehicle Information			
VIN	2	D	9
D	S	4	C
4	8	5	L
0	1	7	6
7	5		
Unit Number	Year	Make	Model
	2005	Decap	38ft Tri/A
Registered Owner's Name		Plate Number	
GN MOTORS LTD		6SH626	
Address		Postal Code	Phone Number
6520 174 AVE NW		T5Y3R2	(780) 993-8081
Drum Brakes:		Disc Brakes:	
A-Full Inspection with Drum Removed			
LEFT FRONT RIGHT			
100 psi	100 psi	419.35 mm	Drums/Rotors
10 mm	11 mm	21 mm	Linings/Pads
		51 mm	Push Rod Travel
100 psi	100 psi	419.35 mm	Drums/Rotors
13 mm	11 mm	21 mm	Linings/Pads
		51 mm	Push Rod Travel
100 psi	100 psi	419.35 mm	Drums/Rotors
12 mm	11 mm	21 mm	Linings/Pads
		51 mm	Push Rod Travel
psi	psi	mm	Drums/Rotors
mm	mm	mm	Linings/Pads
		mm	Push Rod Travel
psi	psi	mm	Drums/Rotors
mm	mm	mm	Linings/Pads
		mm	Push Rod Travel
psi	psi	mm	Drums/Rotors
mm	mm	mm	Linings/Pads
		mm	Push Rod Travel
psi	psi	mm	Drums/Rotors
mm	mm	mm	Linings/Pads
		mm	Push Rod Travel
Park Brake Lining Left N/A mm Right N/A mm Trans N/A mm			
Wheel Torque Checked ☒ Inner N/A ft lbs Outer 500 ft lbs			

VSSRO/2018

P=PASS F=FAIL NA=Not Applicable

Page 1 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train			
Component	P	F	NA
1.2 Exhaust System			
1.12 Gasoline or Diesel Fuel System (LPG, CNG, & LNG) - SEE APPENDIX A*			
NOTES:			
APPENDIX A*			
Component	P	F	NA
A.1 Liquefied Petroleum Gas (LPG or Propane) Fuel System			
A.2 Compressed Natural Gas (CNG) Fuel System			
A.3 Liquefied Natural Gas (LNG) Fuel System			
NOTES:			
Section 2 - Suspension			
Component	P	F	NA
2.1 Suspension & Frame Attachments			
2.2 Axle Attaching & Tracking Components			
2.3 Axle & Axle Assembly			
2.4 Spring & Spring Attachment			
2.5 Air Suspension			
2.6 Self-Steer & Controlled-Steer Axle			
2.7 Shock Absorber/Strut Assembly			
NOTES:			
ALL 6 SHOCKS LEAKING AND LOOSE - TIGHT			
Section 3H - Hydraulic Brakes			
Component	P	F	NA
3H.1 Hydraulic System Components			
3H.6 Air-Over-Hydraulic Brake System			
3H.7 Surge Brake Controller			
3H.8 Vacuum System			
3H.9 Air-Bonsted Trailer Brake System			
3H.10 Electric Brake System			
3H.12 Drum Brake System Components			
3H.13 Disc Brake System Components			
3H.19 Brake Performance			
NOTES:			
Section 3A - Air Brakes			
Component	P	F	NA
3A.3 Air System Leakage			
3A.4 Air Tank			
3A.8 Brake Valves & Controls			
3A.12 Parking Brake & Emergency Application			
3A.13 Air System Components			
3A.14 Brake Chamber			
3A.15 Drum Brake System Components			
3A.16 S-Cam Drum Brake System			
3A.17 Brake Shoe Travel (Wedge Brakes)			
3A.18 Disc Brake System Components			
3A.20 Anti-Lock Brake System (ABS)			
3A.22 Stability Control System (ESC/L or (SSC)			
3A.23 Brake Performance			
NOTES:			
ABS LIGHT ON - REPAIRED			
5 BRAKE SHOES AND 5 DRUMS LOW AND WORN - REPLACED			
Section 4 - Steering			
Component	P	F	NA
4.1 Steering Control & Linkage			
4.4 Kingpin			
4.5 Self-Steer & Controlled-Steer Axle			
NOTES:			

VSSRO/2018

P=PASS F=FAIL NA=Not Applicable

Page 2 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment			
Component	P	F	NA
5.1 Fire Extinguisher			
NOTES:			
Section 6 - Lamps			
Component	P	F	NA
6.1 Required Lamps			
6.2 Reflector			
6.3 Retro-Reflective Marking			
NOTES:			
FRONT R/S MARKER LIGHT NOT WORKING - REPAIRED			
Section 7 - Electrical System			
Component	P	F	NA
7.1 Wiring			
7.2 Battery			
7.3 Trailer Cord (output to towed vehicle)			
NOTES:			
Section 8 - Body			
Component	P	F	NA
8.5 Cargo Body			
8.6 Frame Rails & Mounts			
8.7 Unloaded Body Elements			
8.8 Cab or Cargo Door			
8.9 Cargo Tank or Vessel			
8.10 Body, Device or Equipment Attached or Mounted to the Vehicle			
8.11 Refrigeration/Heater Unit Fuel System			
8.21 Fender Mud Flap			
8.22 Landing Gear on Trailer			
8.23 Sliding Axle Assembly (Sliding Brake)			
8.24 Aerodynamic Device & Attachment			
8.25 Rear Impact Guard (RIG)			
NOTES:			
Section 9 - Tires and Wheels			
Component	P	F	NA
9.1 Tire Tread Depth			
9.2 Tire Tread Condition			
9.3 Tire Sidewall & Manufacturer Markings			
9.4 Tire Inflation Pressure			
9.5 Wheel Hub			
9.6 Wheel Bearing			
9.7 Wheel Rim			
9.8 Multi-Piece Wheel Rim			
9.9 Spoke Wheel/Dismountable Rim System			
9.10 Disc Wheel System			
9.11 Wheel Fasteners (Nuts, Bolts & Shims)			
NOTES:			
Section 10 - Couplers and Hitches			
Component	P	F	NA
10.1 Hitch Assembly, Drawbar & Attaching Components			
10.2 Secondary Attachment (Safety Chain or Cable)			
10.3 Pinch Hook, Pin Hitch, or Coupler Hitch			
10.4 Ball Type Hitch			
10.5 Roll-Coupling Hitch			
10.6 Automated Coupling Device			
10.7 Fifth Wheel Coupler			
10.8 Oscillating Fifth Wheel Coupler			
10.9 Ball-Bearing Type Turntable on Trailer			

VSSRO/2018

P=PASS F=FAIL NA=Not Applicable

Page 3 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:			
Certification			
The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #8741175) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.			
Date of Inspection	Technician Number	Facility Number	Signature
2026/05/09	D1976	19938	
Customer Acknowledgment			Date (Year/Month/Day)
I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			2026/05/09
			Customer Signature

VSSRO/2018

P=PASS F=FAIL NA=Not Applicable

Page 4 of 4

