



80087900008261376

CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Ronco Oilfield Hauling Ltd		
Address:	Box 338		
City:	Medicine Hat	Province:	AB
		Postal Code:	T1A-7G1
Telephone Number:	(403) 526-4873		
Vehicle Identification Number:	2PLG053302BE10674		
Make:	peerl	Model:	PPT-45-5386-3A
Year:	2002	Unit Number:	226
Odometer:	339720 KM	Licence Plate Number:	Z44319
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Ronco Oilfield Hauling Ltd.	12860
Inspection Technician Name:	Technician Number:
Douglas Kromrey	A1251
Inspection Technician Signature:	<i>Douglas Kromrey</i>
Inspection Date:	2025/11/19



CERTIFICATE NUMBER

Commercial Vehicle Registration Certificate

PART 1: GENERAL INFORMATION

Vehicle Identification Number (VIN)	
Make	
Model	
Year	
Weight	
Engine Number	
Station Number	
Model/PT-882-A	
Unit Number	
Plate Number	

PART 2: SIGNATURE

Signature of Technician	
Signature of Inspector	
Facility Number	
Technical Station Number	

Signature

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Trailer										kg									
Vehicle Information																			
VIN	2	P	L	G	0	5	3	3	0	2	B	E	1	0	6	7	4		
Unit Number 226				Year 2002				Make peerl				Model PPT-45-5386-3A				Odometer 339,720			
Registered Owner's Name Ronco Oilfield Hauling Ltd														Plate Number Z44319					
Address Box 338										Postal Code T1A-7G1					Phone Number (403) 526-4873				

Drum Brakes: B-Wheel-on Full Inspection

Disc Brakes:

		LEFT	FRONT	RIGHT		
110 psi	110 psi	16.538 in	Drums/Rotors	16.535 in	110 psi	110 psi
3/8 in	7/16 in	9/16 in	Linings/Pads	5/8 in	5/16 in	5/16 in
		1 3/4 in	Push Rod Travel	1 3/4 in		
110 psi	110 psi	16.561 in	Drums/Rotors	16.565 in	110 psi	110 psi
3/8 in	3/8 in	1/2 in	Linings/Pads	7/16 in	1/2 in	7/16 in
		1 3/4 in	Push Rod Travel	1 3/4 in		
110 psi	110 psi	16.580 in	Drums/Rotors	16.533 in	110 psi	110 psi
7/16 in	7/16 in	1/2 in	Linings/Pads	5/8 in	7/16 in	7/16 in
		1 3/4 in	Push Rod Travel	1 3/4 in		
psi	psi	in	Drums/Rotors	in	psi	psi
in	in	in	Linings/Pads	in	in	in
		in	Push Rod Travel	in		
psi	psi	in	Drums/Rotors	in	psi	psi
in	in	in	Linings/Pads	in	in	in
		in	Push Rod Travel	in		
psi	psi	in	Drums/Rotors	in	psi	psi
in	in	in	Linings/Pads	in	in	in
		in	Push Rod Travel	in		

Park Brake Lining Left n/a in Right n/a in Trans n/a in
 Wheel Torque Checked ☒ Inner 500 ft lbs Outer 500 ft lbs

346 J. N. G. S.

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train								
Component	P	F	NA	Component	P	F	NA	
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓	

NOTES:

APPENDIX "A"								
Component	P	F	NA	Component	P	F	NA	
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓	
A.2. Compressed Natural Gas (CNG) Fuel System			✓					

NOTES:

Section 2 - Suspension								
Component	P	F	NA	Component	P	F	NA	
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓			
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓	
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓			
2.4. Spring & Spring Attachment			✓					

NOTES:

Section 3H - Hydraulic Brakes								
Component	P	F	NA	Component	P	F	NA	
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			✓	
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			✓	
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓	
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓	
3H.9. Air-Boosted Trailer Brake System			✓					

NOTES:

Section 3A - Air Brakes								
Component	P	F	NA	Component	P	F	NA	
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓			
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓	
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓	
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓			
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓	
3A.14. Brake Chamber	✓			3A.23. Brake Performance	✓			
3A.15. Drum Brake System Components	✓							

NOTES:

Section 4 - Steering								
Component	P	F	NA	Component	P	F	NA	
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓	
4.4. Kingpin			✓					

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER SEMI-TRAILER DOLBY CONVERTER

PHOTOS

PHOTOS

PHOTOS

PHOTOS

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)			✓
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body			✓	8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements			✓	8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door			✓	8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle			✓	8.25. Rear Impact Guard (RIG)	✓		

NOTES:


Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System			✓
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components			✓	10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler	✓		
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				




**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8261376) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection 2025/11/19	Technician Number A1251	Facility Number 12860	Signature 
Customer Acknowledgment I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			Date (Year/Month/Day) 2025/11/19
			Customer Signature 

NOT RECOMMENDED FOR REUSE AND OF INSPECTION
NOT RECOMMENDED FOR REUSE AND OF INSPECTION

Handwritten signature in purple ink.

Handwritten initials in purple ink.