



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Ronco Oilfield Hauling Ltd		
Address:	Box 338		
City:	Medicine Hat	Province:	AB
		Postal Code:	T1A-7G1
Telephone Number:	(403) 526-4873		
Vehicle Identification Number:	2PLH0274X4BM11594		
Make:	Peerless	Model:	JP-45-LR-16LP
Year:	2004	Unit Number:	348
Odometer:	42677 KM	Licence Plate Number:	4RW585
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Ronco Oilfield Hauling Ltd.	12860
Inspection Technician Name:	Technician Number:
Douglas Kromrey	A1251
Inspection Technician Signature:	<i>Douglas Kromrey</i>
Inspection Date:	2025/12/03

WATER RESOURCES DIVISION UNITED STATES DEPARTMENT OF THE INTERIOR

The following information was obtained from the records of the Division of Water Resources, Department of the Interior, United States of America.

For further information, please refer to the following pages.

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

WATER RESOURCES DIVISION
UNITED STATES DEPARTMENT OF THE INTERIOR

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Trailer										kg									
Vehicle Information																			
VIN	2	P	L	H	0	2	7	4	X	4	B	M	1	1	5	9	4		
Unit Number 348			Year 2004			Make Peerless			Model JP-45-LR-16LP			Odometer 42,677							
Registered Owner's Name Ronco Oilfield Hauling Ltd															Plate Number 4RW585				
Address Box 338										Postal Code T1A-7G1					Phone Number (403) 526-4873				

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		LEFT	FRONT	RIGHT		
110 psi	110 psi	12.248 in	Drums/Rotors	12.246 in	110 psi	110 psi
3/8 in	7/16 in	11/16 in	Linings/Pads	11/16 in	7/16 in	1/2 in
		1 3/4 in	Push Rod Travel	1 3/4 in		
110 psi	110 psi	12.248 in	Drums/Rotors	12.248 in	110 psi	110 psi
7/16 in	7/16 in	11/16 in	Linings/Pads	11/16 in	3/8 in	3/8 in
		1 3/4 in	Push Rod Travel	1 3/4 in		
psi	psi	in	Drums/Rotors	in	psi	psi
in	in	in	Linings/Pads	in	in	in
		in	Push Rod Travel	in		
psi	psi	in	Drums/Rotors	in	psi	psi
in	in	in	Linings/Pads	in	in	in
		in	Push Rod Travel	in		
psi	psi	in	Drums/Rotors	in	psi	psi
in	in	in	Linings/Pads	in	in	in
		in	Push Rod Travel	in		
psi	psi	in	Drums/Rotors	in	psi	psi
in	in	in	Linings/Pads	in	in	in
		in	Push Rod Travel	in		
Park Brake Lining Left <u>n/a</u> in Right <u>n/a</u> in Trans <u>n/a</u> in Wheel Torque Checked ☒ Inner <u>500</u> ft lbs Outer <u>500</u> ft lbs						

COMMERCIAL VEHICLE RECORD INFORMATION
TALLER, SEMI-TRAILER, COUNTRY, COUNTRY ONLY

Section 2 - In case of emergency

NOTES:

NOTES:

NOTES:

NOTES:

NOTES:

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector			✓				

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body			✓	8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts			✓	8.21. Fender/Mud Flap			✓
8.7. Unitized Body Elements			✓	8.22. Landing Gear on Trailer			✓
8.8. Cab or Cargo Door			✓	8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle			✓	8.25. Rear Impact Guard (RIG)			✓

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System			✓
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

forward axle tires 3/8, 7/16, 3/8, 7/16, 3/8, 3/8, 7/16, 1/2
rear axle 7/16, 7/16, 3/8, 3/8, 7/16, 3/8, 3/8, 3/8

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components			✓	10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler	✓		
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8261381) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2025/12/03	A1251	12860	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2025/12/03

Customer Signature

