



Commercial Vehicle Inspection Certificate Traffic Safety Act


PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:		
GVW:	kg	Brake Type:	Air	
Owner Name:	BUFFALO PARCEL COURIER SERVICES LTD			
Address:	11310 153 ST NW			
City:	EDMONTON	Province:	AB	Postal Code: T5M1X6
Telephone Number:	(780) 455-1677			
Vehicle Identification Number:	1UYVS2536DU758701			
Make:	Utility	Model:	Reefer	
Year:	2013	Unit Number:	T701	
Odometer:	92609 KM	Licence Plate Number:	6BR967	Province: AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
1975106 AB Ltd.	19647
Inspection Technician Name:	Technician Number:
Ashley Jesso	C9248
Inspection Technician Signature:	
Inspection Date:	2026/07/15

