



**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	CROWN STAR TRANSPORT		
Address:	10158 46 ST NE		
City:	CALGARY	Province:	AB
		Postal Code:	T3J2B5
Telephone Number:	(000) 000-0000		
Vehicle Identification Number:	1FUJGBDV8JLJM9847		
Make:	FREIGHTLINER	Model:	CASCADIA
Year:	2018	Unit Number:	1979
Odometer:	1097080 KM	Licence Plate Number:	
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Capital Truck and Trailer Repair Ltd.	19348
Inspection Technician Name:	Technician Number:
David Huayhualla Aguado	C3327
Inspection Technician Signature:	
Inspection Date:	2026/03/23