



CV8598083



80087500008598083

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	HRYNIUK TRUCKING LTD		
Address:	18131 84 AVE NW		
City:	EDMONTON	Province:	AB
		Postal Code:	T5T0R7
Telephone Number:	(780) 481-1374		
Vehicle Identification Number:	2K9KB22516L052057		
Make:	Gerry's	Model:	-
Year:	2006	Unit Number:	238J
Odometer:	KM	Licence Plate Number:	943NSF
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Fort Garry Industries Ltd	10351
Inspection Technician Name:	Technician Number:
Michel Langlois	A4455
Inspection Technician Signature:	
Inspection Date:	2026/07/30

Replaces certificate number: CV8598057



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	HRYNIUK TRUCKING LTD		
Address:	18131 84 AVE NW		
City:	EDMONTON	Province:	AB
Postal Code:	T5T0R7		
Telephone Number:	(780) 481-1374		
Vehicle Identification Number:	2K9KB22516L052057		
Make:	Gerry's	Model:	-
Year:	2006	Unit Number:	238J
Odometer:	KM	Licence Plate Number:	943NSF
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Fort Garry Industries Ltd	10351
Inspection Technician Name:	Technician Number:
Joshua Steward	C9143
Inspection Technician Signature:	
Inspection Date:	2026/07/30

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Trailer										kg									
Vehicle Information																			
VIN	2	K	9	K	B	2	2	5	1	6	L	0	5	2	0	5	7		
Unit Number 238J				Year 2006				Make Gerry's				Model -				Odometer			
Registered Owner's Name HRYNIUK TRUCKING LTD														Plate Number 943NSF					
Address 18131 84 AVE NW										Postal Code T5T0R7				Phone Number (780) 481-1374					

Drum Brakes: C-Limited Inspection	Disc Brakes:
--	---------------------

		<u>LEFT</u>		<u>FRONT</u>		<u>RIGHT</u>			
100 psi	100 psi	NA mm	Drums/Rotors	NA mm		NA mm	Drums/Rotors	100 psi	100 psi
14 mm	14 mm	15 mm	Linings/Pads	18 mm		18 mm	Linings/Pads	14 mm	14 mm
		41.2 mm	Push Rod Travel	41.2 mm		41.2 mm	Push Rod Travel		
100 psi	100 psi	NA mm	Drums/Rotors	NA mm		NA mm	Drums/Rotors	100 psi	100 psi
14 mm	14 mm	20 mm	Linings/Pads	15 mm		15 mm	Linings/Pads	14 mm	14 mm
		41.2 mm	Push Rod Travel	41.2 mm		41.2 mm	Push Rod Travel		
psi	psi	mm	Drums/Rotors	mm		mm	Drums/Rotors	psi	psi
mm	mm	mm	Linings/Pads	mm		mm	Linings/Pads	mm	mm
		mm	Push Rod Travel	mm		mm	Push Rod Travel		
psi	psi	mm	Drums/Rotors	mm		mm	Drums/Rotors	psi	psi
mm	mm	mm	Linings/Pads	mm		mm	Linings/Pads	mm	mm
		mm	Push Rod Travel	mm		mm	Push Rod Travel		
psi	psi	mm	Drums/Rotors	mm		mm	Drums/Rotors	psi	psi
mm	mm	mm	Linings/Pads	mm		mm	Linings/Pads	mm	mm
		mm	Push Rod Travel	mm		mm	Push Rod Travel		
psi	psi	mm	Drums/Rotors	mm		mm	Drums/Rotors	psi	psi
mm	mm	mm	Linings/Pads	mm		mm	Linings/Pads	mm	mm
		mm	Push Rod Travel	mm		mm	Push Rod Travel		

Park Brake Lining Left NA mm Right NA mm Trans NA mm

Wheel Torque Checked ☒ Inner NA ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment			✓				

NOTES:

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓		
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)			✓
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance			✓
3A.15. Drum Brake System Components	✓						

NOTES:

AIR LINES @ FRONT AXLE BY VALVE NEEDS PROTECTION-DONE
AIR LINES AT FRONT AIR TANK HAVE CRACKS AT FITTINGS-REPAIRED
R.F MAXI SPRING BROKEN-REPLACED

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin			✓				

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)			✓
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body			✓	8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Uniltized Body Elements	✓			8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door			✓	8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle			✓	8.25. Rear Impact Guard (RIG)			✓

NOTES:

L.S LANDING GEAR TOP CAP RUSTED THROUGH-REPLACED

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System			✓
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

R.R.O TIRE VALVE STEM LEAKING-REPAIRED

L.R.I & R.F.I MISSING VALVE STEM CAPS-REPLACED

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler	✓		
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 10 - Couplers and Hitches							
Component	P	F	NA	Component	P	F	NA
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

NOTES:
 ADJUST 5TH WHEEL-DONE

Certification
 The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #8598057)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection 2026/07/30	Technician Number C9143	Facility Number 10351	Signature 
---	-----------------------------------	---------------------------------	--

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.	Date (Year/Month/Day) 2026/07/30 Customer Signature
---	---