



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	34200 kg	Brake Type:	Air
Owner Name:	OSCO MUDJACKING AND CONSTRUCTION LTD.		
Address:	4174 95 Street		
City:	Edmonton	Province:	AB
		Postal Code:	T6E6H5
Telephone Number:	(780) 699-1682		
Vehicle Identification Number:	2FZPAZDE37AY48607		
Make:	Sterling	Model:	Sterling
Year:	2007	Unit Number:	21
Odometer:	239615 KM	Licence Plate Number:	13N928
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Action Muffler Auto Repairs Southside Ltd.	21666
Inspection Technician Name:	Technician Number:
Gary Sbitney	A8075
Inspection Technician Signature:	
Inspection Date:	2025/11/07

