



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**


**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	63500 kg	Brake Type:	Air
Owner Name:	FRT SOLUTION INCORPORATED		
Address:	179 SAGE HILL GREEN NW		
City:	CALGARY	Province:	AB
Postal Code:	T3R0G8		
Telephone Number:	(403) 801-8708		
Vehicle Identification Number:	1XKWD40X8HJ988433		
Make:	Kenworth	Model:	Construct
Year:	2017	Unit Number:	2102
Odometer:	823299 KM	Licence Plate Number:	A30901
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Global Truck Repair Ltd.	19904
Inspection Technician Name:	Technician Number:
Royce McDonald	B0593
Inspection Technician Signature:	
Inspection Date:	2026/08/07