



Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	J & A Kendze Septic Services Ltd		
Address:	Site 9 Box 8 RR1		
City:	Didsbury	Province:	AB
Postal Code:	TOMOWO		
Telephone Number:	(403) 559-6588		
Vehicle Identification Number:	2MFB2R5D5PR009936		
Make:	Midland	Model:	SLX3 End Dump
Year:	2023	Unit Number:	
Odometer:	KM	Licence Plate Number:	6JT817
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
1816678 Alberta Ltd.	19509
Inspection Technician Name:	Technician Number:
Jamie Royston	C4639
Inspection Technician Signature:	
Inspection Date:	2026/08/26