



80087300008609351

CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	North of 55 Oilfield Hauling Ltd		
Address:	Box 618		
City:	Slave Lake	Province:	AB
Postal Code:	T0G2A0		
Telephone Number:	(780) 849-4333		
Vehicle Identification Number:	2PLH024276BK12380		
Make:	Peerless	Model:	Jeep
Year:	2006	Unit Number:	16J2
Odometer:	58033 KM	Licence Plate Number:	6FM720
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Rymut Mechanical	18667
Inspection Technician Name:	Technician Number:
Michael MacDonald	A7768
Inspection Technician Signature:	
Inspection Date:	2026/03/16

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Trailer										kg									
Vehicle Information																			
VIN	2	P	L	H	0	2	4	2	7	6	B	K	1	2	3	8	0		
Unit Number 16J2				Year 2006				Make Peerless				Model Jeep				Odometer 58,033			
Registered Owner's Name North of 55 Oilfield Hauling Ltd														Plate Number 6FM720					
Address Box 618										Postal Code T0G2A0				Phone Number (780) 849-4333					

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		LEFT	FRONT	RIGHT		
96 psi	75 psi	311.98 mm	Drums/Rotors	312.48 mm	95 psi	100 psi
9 mm	12 mm	15 mm	Linings/Pads	15 mm	11 mm	11 mm
		40 mm	Push Rod Travel	43 mm		
110 psi	100 psi	312.26 mm	Drums/Rotors	312.22 mm	98 psi	100 psi
11 mm	12 mm	13 mm	Linings/Pads	12 mm	11 mm	11 mm
		45 mm	Push Rod Travel	47 mm		
			Drums/Rotors			
			Linings/Pads			
			Push Rod Travel			
			Drums/Rotors			
			Linings/Pads			
			Push Rod Travel			
			Drums/Rotors			
			Linings/Pads			
			Push Rod Travel			
			Drums/Rotors			
			Linings/Pads			
			Push Rod Travel			

Park Brake Lining Left na mm Right na mm Trans na mm
Wheel Torque Checked ☒ Inner na ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train						
Component	P	F	NA	Component	P	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*		✓

NOTES:

APPENDIX "A"						
Component	P	F	NA	Component	P	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System		✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓			

NOTES:

Section 2 - Suspension						
Component	P	F	NA	Component	P	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension		✓
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle		✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly		✓
2.4. Spring & Spring Attachment			✓			

NOTES:

Section 3H - Hydraulic Brakes						
Component	P	F	NA	Component	P	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System		✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components		✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components		✓
3H.8. Vacuum System			✓	3H.19. Brake Performance		✓
3H.9. Air-Boosted Trailer Brake System			✓			

NOTES:

Section 3A - Air Brakes						
Component	P	F	NA	Component	P	NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓	
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)		✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components		✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)		✓
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)		✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance		✓
3A.15. Drum Brake System Components	✓					

NOTES:

3A.15 Drum limits 311.15-314.20mm

Inside set measurements IS=inside, OS= Outside

#1L IS D=311.82MM, S=13MM, PR=40MM #1R IS D=311.93MM, S=11. PR=45

#2L IS D=312.40 MM, S=14MM, PR=47. #2R IS D=312.25, S=13MM, PR=45MM

3A.16 Autoslack anchor pins/bushings missing or damaged, #1L IS/OS, #1R, OS, #2L IS/OS #2R IS

Defects Corrected. All brakes set to 30mm push rod travel, Repairs Completed on WO 16J2 2026 mar 12

COMMERCIAL VEHICLE RECORD OF INSPECTION **TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

Section 4 - Steering						
Component	P	F	NA	Component	P	F NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle		✓
4.4. Kingpin			✓			

NOTES:

Section 5 - Instruments and Auxiliary Equipment						
Component	P	F	NA	Component	P	F NA
5.1. Fire Extinguisher			✓			

NOTES:

Section 6 - Lamps						
Component	P	F	NA	Component	P	F NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓	
6.2. Reflex Reflector	✓					

NOTES:

6.1 #1L Corner marker light box damaged

Defects Corrected

Section 7 - Electrical System						
Component	P	F	NA	Component	P	F NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓	
7.2. Battery	✓					

NOTES:

Section 8 - Body						
Component	P	F	NA	Component	P	F NA
8.5. Cargo Body			✓	8.11. Refrigeration/Heater Unit Fuel System		✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓	
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer		✓
8.8. Cab or Cargo Door			✓	8.23. Sliding Axle Assembly (Sliding Bogie)		✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment		✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)	✓	

NOTES:

8.10 tie down D-Ring missing L side. D-ring R side crack in welds, center rear air bag under lift 5th wheel damaged.

Defects Corrected

Section 9 - Tires and Wheels						
Component	P	F	NA	Component	P	F NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓	
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim		✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System		✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓	
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓	
9.6. Wheel Bearing	✓					

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:

Inside set measurements

#1L IS, T=7MM 110PSI, #1L OS T=8MM, 110PSI #1R IS T=12MM 100PSI #1R OS 12 100

#2 L IS T=10MM, 98PSI, #2RIS T=11 100PSI, , #2R IS T= 11 100PSI, #2R,OS 11 100PSI

9.2 #1L IS set replace, IS tread separation, OS chunking

9.4 All tires adjusted to 110psi

9.5 #1LOS Wheel seal

9.11 #1R IS 2 wheel nuts blew apart

Defects Corrected

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler	✓		
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8609351) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection 2026/03/16	Technician Number A7768	Facility Number 18667	Signature 
---	-----------------------------------	---------------------------------	--

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/03/16

Customer Signature