



**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	North of 55 Oilfield Hauling Ltd		
Address:	Box 618		
City:	Slave Lake	Province:	AB
		Postal Code:	T0G2A0
Telephone Number:	(780) 849-4333		
Vehicle Identification Number:	2E9C45C4483003131		
Make:	Scona	Model:	Jeep
Year:	2008	Unit Number:	16J3
Odometer:	8066 KM	Licence Plate Number:	6TD496
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Rymut Mechanical	18667
Inspection Technician Name:	Technician Number:
Michael MacDonald	A7768
Inspection Technician Signature:	<i>End</i>
Inspection Date:	2026/06/04

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Trailer										kg									
Vehicle Information																			
VIN	2	E	9	C	4	5	C	4	4	8	3	0	0	3	1	3	1		
Unit Number 16J3			Year 2008			Make Scona			Model Jeep			Odometer 8,066							
Registered Owner's Name North of 55 Oilfield Hauling Ltd															Plate Number 6TD496				
Address Box 618										Postal Code T0G2A0			Phone Number (780) 849-4333						

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		LEFT		FRONT		RIGHT			
100 psi	100 psi	313.21 mm	Drums/Rotors	311.80 mm		100 psi	100 psi		
9 mm	9 mm	19 mm	Linings/Pads	16 mm		8 mm	10 mm		
		30 mm	Push Rod Travel	30 mm					
100 psi	100 psi	312.46 mm	Drums/Rotors	312.40 mm		100 psi	100 psi		
10 mm	8 mm	15 mm	Linings/Pads	19 mm		10 mm	8 mm		
		30 mm	Push Rod Travel	30 mm					
psi	psi	mm	Drums/Rotors	mm		psi	psi		
mm	mm	mm	Linings/Pads	mm		mm	mm		
		mm	Push Rod Travel	mm					
psi	psi	mm	Drums/Rotors	mm		psi	psi		
mm	mm	mm	Linings/Pads	mm		mm	mm		
		mm	Push Rod Travel	mm					
psi	psi	mm	Drums/Rotors	mm		psi	psi		
mm	mm	mm	Linings/Pads	mm		mm	mm		
		mm	Push Rod Travel	mm					
psi	psi	mm	Drums/Rotors	mm		psi	psi		
mm	mm	mm	Linings/Pads	mm		mm	mm		
		mm	Push Rod Travel	mm					

Park Brake Lining Left na mm Right na mm Trans na mm

Wheel Torque Checked ☒ Inner na ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train								
Component	P	F	NA	Component	P	F	NA	
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓	

NOTES:

APPENDIX "A"								
Component	P	F	NA	Component	P	F	NA	
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓	
A.2. Compressed Natural Gas (CNG) Fuel System			✓					

NOTES:

Section 2 - Suspension								
Component	P	F	NA	Component	P	F	NA	
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension			✓	
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓	
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly			✓	
2.4. Spring & Spring Attachment			✓					

NOTES:

Section 3H - Hydraulic Brakes								
Component	P	F	NA	Component	P	F	NA	
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			✓	
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			✓	
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓	
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓	
3H.9. Air-Boosted Trailer Brake System			✓					

NOTES:

Section 3A - Air Brakes								
Component	P	F	NA	Component	P	F	NA	
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓			
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓	
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓	
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)			✓	
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓	
3A.14. Brake Chamber	✓			3A.23. Brake Performance			✓	
3A.15. Drum Brake System Components	✓							

NOTES:

Wheeler set up OS= outside IS= inside set. 12.25" drums 311.20-314.40mm
 #1L IS drum = 312.30mm Shoe=15mm Rod=30mm #1R IS drum=311.40 shoe=16mm rod=30mm
 #2L IS drum = 313.86mm Shoe=16mm Rod=30mm #2R IS drum=311.60 shoe=16mm rod=30

3A.16 #1L OS Shoes, S-cam, backing plate, auto slack. #2L IS Shoes, backing plate. #2R OS shoes
 3A.13 Replaced air lines relay to #1R IS & OS

Defects corrected WO 2026 jun 04 16J3

COMMERCIAL VEHICLE RECORD OF INSPECTION **TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin			✓				

NOTES:

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

6.1 L brake lamp

Defects corrected

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body			✓	8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer			✓
8.8. Cab or Cargo Door			✓	8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)	✓		

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

9.5 #1L IS wheel bearings and seal replaced
Wheels torqued 500 # ft

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 10 - Couplers and Hitches						
Component	P	F	NA	Component	P	F NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device		✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler	✓	
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler		✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer		✓
10.5. Roll-Coupling Hitch			✓			

NOTES:

10.1 chaffed air bag under 5th wheel lift

Defects corrected

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8737324) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/06/04	A7768	18667	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/06/04

Customer Signature