



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Site Resource Group GP Corporation		
Address:	Box 210		
City:	Cold Lake	Province:	AB
Postal Code:	T9M1P1		
Telephone Number:	(780) 826-0369		
Vehicle Identification Number:	2E9L50F3973003157		
Make:	Scona	Model:	NA
Year:	2007	Unit Number:	106-017
Odometer:	KM	Licence Plate Number:	6VX951
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Site Resource Group GP Corporation	21951
Inspection Technician Name:	Technician Number:
Jasen Reaume	C4695
Inspection Technician Signature:	
Inspection Date:	2026/07/21