



Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	West Central Contracting Ltd.		
Address:	450 East River Rd		
City:	Hinton	Province:	AB
		Postal Code:	T7V2G3
Telephone Number:	(780) 865-3000		
Vehicle Identification Number:	2M9PF4848DP016110		
Make:	arctic	Model:	HR48-TR-Q
Year:	2013	Unit Number:	L2002
Odometer:	KM	Licence Plate Number:	6JY319
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Werner Heavy Equipment Repair Ltd.	12962
Inspection Technician Name:	Technician Number:
Sheldon Werner	A8976
Inspection Technician Signature:	
Inspection Date:	2026/09/02


CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act


PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	West Central Contracting Ltd.		
Address:	450 East River Rd		
City:	Hinton	Province:	AB
Postal Code:	T7V2G3		
Telephone Number:	(780) 865-3000		
Vehicle Identification Number:	2M9PF4848DP016110		
Make:	arctic	Model:	HR48-TR-Q
Year:	2013	Unit Number:	L2002
Odometer:	KM	Licence Plate Number:	6JY319
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Werner Heavy Equipment Repair Ltd.	12962
Inspection Technician Name:	Technician Number:
Sheldon Werner	A8976
Inspection Technician Signature:	
	
Inspection Date:	2026/09/02

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Trailer										kg									
Vehicle Information																			
VIN	2	M	9	P	F	4	8	4	8	D	P	0	1	6	1	1	0		
Unit Number L2002				Year 2013				Make arctic				Model HR48-TR-Q				Odometer			
Registered Owner's Name West Central Contracting Ltd.															Plate Number 6JY319				
Address 450 East River Rd										Postal Code T7V2G3					Phone Number (780) 865-3000				

Drum Brakes: B-Wheel-on Full Inspection

Disc Brakes:

		<u>LEFT</u>		<u>FRONT</u>		<u>RIGHT</u>			
90 psi	90 psi	420.5 mm	mm	Drums/Rotors		420.52 mm	mm	90 psi	90 psi
2.4 mm	4.5 mm	15 mm	mm	Linings/Pads		14 mm	mm	4 mm	3 mm
		21 mm	mm	Push Rod Travel		21 mm	mm		
90 psi	90 psi	420.5 mm	mm	Drums/Rotors		420.2 mm	mm	90 psi	90 psi
2.8 mm	2.5 mm	16 mm	mm	Linings/Pads		15 mm	mm	1.75 mm	3 mm
		21 mm	mm	Push Rod Travel		21 mm	mm		
90 psi	90 psi	420.5 mm	mm	Drums/Rotors		420.5 mm	mm	90 psi	90 psi
2.74 mm	3 mm	17 mm	mm	Linings/Pads		18 mm	mm	2 mm	2.5 mm
		21 mm	mm	Push Rod Travel		21 mm	mm		
psi	psi	mm	mm	Drums/Rotors		mm	mm	psi	psi
mm	mm	mm	mm	Linings/Pads		mm	mm	mm	mm
		mm	mm	Push Rod Travel		mm	mm		
psi	psi	mm	mm	Drums/Rotors		mm	mm	psi	psi
mm	mm	mm	mm	Linings/Pads		mm	mm	mm	mm
		mm	mm	Push Rod Travel		mm	mm		
psi	psi	mm	mm	Drums/Rotors		mm	mm	psi	psi
mm	mm	mm	mm	Linings/Pads		mm	mm	mm	mm
		mm	mm	Push Rod Travel		mm	mm		

Park Brake Lining Left na mm Right na mm Trans na mm

Wheel Torque Checked ☒ Inner na ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment			✓				

NOTES:

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓		
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓		
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance			✓
3A.15. Drum Brake System Components	✓						

NOTES:

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin	✓						

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking			✓
6.2. Reflex Reflector	✓						

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door	✓			8.23. Sliding Axle Assembly (Sliding Bogie)	✓		
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle			✓	8.25. Rear Impact Guard (RIG)	✓		

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler			✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #8360995)** the inspection and I certify It has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection

2026/09/02

Technician Number

A8976

Facility Number

12962

Signature



Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/09/02

Customer Signature