



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	34000 kg	Brake Type:	Air
Owner Name:	Pitbull Energy services inc		
Address:	2424 91 ave nw		
City:	Edmonton	Province:	AB
Postal Code:	T9E7E8		
Telephone Number:	(855) 748-2866		
Vehicle Identification Number:	5KKPALBG3BPAZ7455		
Make:	Western Star	Model:	WB123086S
Year:	2011	Unit Number:	W329
Odometer:	44 KM	Licence Plate Number:	U86970
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Pitbull Energy Services Inc.	18412
Inspection Technician Name:	Technician Number:
Kenneth MacGregor	C8226
Inspection Technician Signature:	
Inspection Date:	2025/10/09

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle Truck										Gross Vehicle Weight registered 34000 kg									
Vehicle Information																			
VIN	5	K	K	P	A	L	B	G	3	B	P	A	Z	7	4	5	5		
Unit Number W329				Year 2011				Make Western Star				Model WB123086S				Odometer 44			
Registered Owner's Name Pitbull Energy services inc																Plate Number U86970			
Address 2424 91 ave nw												Postal Code T9E7E8				Phone Number (855) 748-2866			

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes: D-Full Inspection Wheel Removed

		<u>LEFT</u>		<u>FRONT</u>		<u>RIGHT</u>			
110 psi	14 mm	419.25 mm	Drums/Rotors	419.12 mm		110 psi	14 mm		
		18 mm	Linings/Pads	18 mm					
		31.75 mm	Push Rod Travel	31.75 mm					
100 psi	100 psi	419.23 mm	Drums/Rotors	419.12 mm		100 psi	100 psi		
17 mm	17 mm	18 mm	Linings/Pads	18 mm		18 mm	18 mm		
		38.1 mm	Push Rod Travel	38.1 mm					
100 psi	100 psi	419.26 mm	Drums/Rotors	419.25 mm		100 psi	100 psi		
18 mm	19 mm	18 mm	Linings/Pads	20 mm		18 mm	18 mm		
		38.1 mm	Push Rod Travel	38.1 mm					
100 psi	100 psi	419.26 mm	Drums/Rotors	419.73 mm		100 psi	100 psi		
16 mm	16 mm	18 mm	Linings/Pads	20 mm		17 mm	18 mm		
		38.1 mm	Push Rod Travel	38.1 mm					
psi	psi	mm	Drums/Rotors	mm		psi	psi		
mm	mm	mm	Linings/Pads	mm		mm	mm		
		mm	Push Rod Travel	mm					
psi	psi	mm	Drums/Rotors	mm		psi	psi		
mm	mm	mm	Linings/Pads	mm		mm	mm		
		mm	Push Rod Travel	mm					

Park Brake Lining Left na mm Right na mm Trans na mm
Wheel Torque Checked ☒ Inner 500 ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.1. Accelerator Pedal/Throttle Actuator	✓			1.8. Engine Start Safety Feature			✓
1.2. Exhaust System	✓			1.9. Gear Position Indicator	✓		
1.3. Emission Control Systems and Devices			✓	1.10. Engine or Accessory Drive Belt	✓		
1.4. Drive Shaft	✓			1.11. Hybrid Electric Vehicle & Electric Vehicle Power Train System			✓
1.5. Clutch and Clutch Pedal	✓			1.12. Gasoline or Diesel Fuel System	✓		
1.6. Engine/Transmission Mount	✓			1.13. Pressurized or Liquefied Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓
1.7. Engine/Shut Down	✓						

NOTES:

1.2 oil leaking out of exhaust manifold ports 5,
1.4 yoke nut loose on output of diff #1 going to diff #2
1.2 removed and replaced cylinder head on engine and exhaust manifold gaskets to correct oil from leaking out the exhaust ports from valves,
1.4 removed yoke nut and replaced with new yoke nut and red loctite,

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer and Controlled-Steer Axle	✓		
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment	✓						

NOTES:

2.1, 2.2, 2.4 spring eye bushing axle #2 D/S P/S pushing out / rubbing spring hanger,
spring eye bushing axle #3 D/S pushing out/ rubbing spring hanger,
front D/S has to short of bolt in leaf spring shackle,
2.1, 2.2, 2.4 removed and replaced old spring eye bushings on #2 axle both D/S and P/S as well as wear pads to,
removed and replaced spring eye bushing on D/S #3 axle and wear pads to

2.2 removed and replaced bolt that was to short for shack on front right side of steer axle,

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.13. Disc Brake System Components			✓
3H.2. Brake Pedal/Actuator			✓	3H.14. Mechanical Parking Brake			✓
3H.3. Vacuum Assist (Boost) System			✓	3H.15. Spring-Applied Air-Released Parking Brake			✓
3H.4. Hydraulic Assist (Boost) System			✓	3H.16. Spring-Applied Hydraulic-Released Parking Brake			✓
3H.5. Air Assist (Boost) System			✓	3H.17. Anti-Lock Brake System (ABS)			✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.18. Stability Control System			✓
3H.11. Brake System Indicator Lamps			✓	3H.19. Brake Performance			✓
3H.12. Drum Brake System Components			✓				

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.1. Air Compressor	✓			3A.13. Air System Components	✓		
3A.2. Air Supply System	✓			3A.14. Brake Chamber	✓		
3A.4. Air Tank	✓			3A.15. Drum Brake System Components	✓		
3A.5. Air Tank Check Valves	✓			3A.16. S-Cam Drum Brake System	✓		
3A.6. Brake Pedal/Actuator	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.7. Treadle Valve and Trailer Hand Valve	✓			3A.18. Disc Brake System Components			✓
3A.8. Brake Valves & Controls	✓			3A.19. Anti-Lock Brake System (ABS)	✓		
3A.9. Proportioning, Inversion or Modulation Valve	✓			3A.21. Stability Control System	✓		
3A.10. Towing Vehicle (Tractor) Protection System	✓			3A.23. Brake Performance	✓		
3A.11. Parking Brake & Emergency Application	✓						

NOTES:

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control and Linkage	✓			4.4. Kingpin	✓		
4.2. Power Steering System (Hydraulic and Electric)	✓			4.5. Self-Steer and Controlled-Steer Axle	✓		
4.3. Steering Operation (Active Steer Axle)	✓						

NOTES:

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher	✓			5.8. Heater & Windshield Defroster	✓		
5.2. Hazard Warning Kit	✓			5.9. Fuel-Burning Auxiliary Heater			✓
5.3. Horn	✓			5.10. Chain/"Headache" Rack	✓		
5.5. Speedometer	✓			5.11. Auxiliary Controls and Devices	✓		
5.6. Odometer	✓			5.12. Auxiliary Drive Controls	✓		
5.7. Windshield Wiper/Washer	✓						

NOTES:

5.1 fire extinguisher was out date
 5.3 horn button missing clock spring wore out on contact
 5.1 removed old fire extinguisher from unit and replaced with new fire extinguisher on unit,
 5.3 removed old clock spring and replaced with new clock spring and horn button horn works good,

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.4. Instrument Panel Lamps	✓		
6.2. Reflex Reflector	✓			6.5. Headlamp Aim	✓		
6.3. Retro-Reflective Marking	✓						

NOTES:

6.1 tail light 90% burnt out at the rear of tank on unit,
 6.1 removed old tail light replaced with new led tail works good,

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery	✓						

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.1. Hood or Engine Enclosure	✓			8.12. Bumper	✓		
8.2. Tilt Cab			✓	8.13. Windshield	✓		
8.3. Air-Suspended Cab	✓			8.14. Side Windows	✓		
8.4. Cab and Passenger-Vehicle Body	✓			8.15. Rear Window	✓		
8.5. Cargo Body	✓			8.16. Interior Sun Visor	✓		
8.6. Frame, Rails & Mounts	✓			8.17. Exterior Windshield Sun Visor	✓		
8.7. Unitized Body Elements	✓			8.18. Rear-View Mirror			✓
8.8. Cab or Cargo Door	✓			8.19. Seat	✓		
8.9. Cargo Tank or Vessel	✓			8.20. Seat Belt/Occupant Restraint	✓		
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.21. Fender/Mud Flap	✓		
8.11. Refrigeration/Heater Unit Fuel System (Reefer or Auxiliary Power Unit (APU))			✓	8.24. Aerodynamic Device & Attachment	✓		

NOTES:

8.9 tank has multiple holes in it at the back that need to be welded up,
8.9 rear of tank has plates welded on it to fix holes at rear of tank,

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim (Applies to all wheel types)	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System			✓
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts and Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

9.5 wheel seal leaking on hub front right drive Axel,
9.5 removed wheel hub and seal and bearing cleaned old bearings and reinstalled new seal and clean bearings,
9.4 adjusted the tire pressures on steers to 110 and drives to 100 psi,

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.5. Roll-Coupling Hitch	✓		
10.2. Secondary Attachment (Safety Chain or Cable)	✓			10.6. Automated Coupling Device			✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch	✓			10.7. Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8329316) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection 2025/10/09	Technician Number C8226	Facility Number 18412	Signature
---	-----------------------------------	---------------------------------	-----------

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)
2025/10/09

Customer Signature