



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Hydro-Vacs Unlimited Sales Inc.		
Address:	2340 - 28 Ave SW		
City:	Edmonton	Province:	AB
		Postal Code:	T6X 1A3
Telephone Number:	(000) 000-0000		
Vehicle Identification Number:	5KKPALD188EPFU843		
Make:	Westernstar	Model:	W4900-
Year:	2013	Unit Number:	
Odometer:	155706 KM	Licence Plate Number:	
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Stony Grove Holdings Inc.	21721
Inspection Technician Name:	Technician Number:
Marshall Lealand	A2967
Inspection Technician Signature:	
Inspection Date:	2026/05/01



COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle Truck										Gross Vehicle Weight (kg) kg														
VIN 5 K K P A L D 1 8 8 E P F U 8 4 3																								
Unit Number					Year 2013					Make Westernstar					Model W4900-					Odometer 155,766				
Registered Owner's Name Hydro-Vacs Unlimited Sales Inc.															Plate Number									
Address 2340 - 28 Ave SW										Postal Code T6X 1A3					Phone Number (000) 000-0000									
Drum Brakes: A-Pull Inspection with Drum Removed										Disc Brakes:														

LEFT		FRONT		RIGHT	
110 psi	12.55 mm	419.49 mm	Drums/Rotors	419.07 mm	110 psi
		10.06 mm	Linings/Pads	10.26 mm	12.12 mm
		32 mm	Push Rod Travel	32 mm	
100 psi	12.20 mm	420.14 mm	Drums/Rotors	420.11 mm	100 psi
100 psi	15.70 mm	9.29 mm	Linings/Pads	8.97 mm	100 psi
		31 mm	Push Rod Travel	32 mm	10.19 mm
100 psi	14.69 mm	420.55 mm	Drums/Rotors	419.12 mm	100 psi
100 psi	9.82 mm	10.69 mm	Linings/Pads	11.23 mm	100 psi
		35 mm	Push Rod Travel	35 mm	10.85 mm
100 psi	13.25 mm	420.69 mm	Drums/Rotors	420.77 mm	100 psi
100 psi	12.76 mm	9.57 mm	Linings/Pads	10.90 mm	100 psi
		35 mm	Push Rod Travel	36 mm	13.77 mm
psi	mm	mm	Drums/Rotors	mm	psi
mm	mm	mm	Linings/Pads	mm	mm
mm	mm	mm	Push Rod Travel	mm	mm
psi	mm	mm	Drums/Rotors	mm	psi
mm	mm	mm	Linings/Pads	mm	mm
mm	mm	mm	Push Rod Travel	mm	mm

Park Brake Lining Left **N/A** mm Right **N/A** mm Trans **N/A** mm

Wheel Torque Checked ☒ Inner **N/A** ft lbs Outer **560** ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Component	Pass	Fail	Not Applicable	Component	Pass	Fail	Not Applicable
1.1. Accelerator Pedal/Throttle Actuator	✓			1.8. Engine Start Safety Feature	✓		
1.2. Exhaust System	✓			1.9. Gear Position Indicator			✓
1.3. Emission Control Systems and Devices	✓			1.10. Engine or Accessory Drive Belt	✓		
1.4. Drive Shaft	✓			1.11. Hybrid Electric Vehicle & Electric Vehicle Power Train System			✓
1.5. Clutch and Clutch Pedal	✓			1.12. Gasoline or Diesel Fuel System	✓		
1.6. Engine/Transmission Mount	✓			1.13. Pressurized or Liquefied Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓
1.7. Engine/Shutdown	✓						

NOTES:

Component	Pass	Fail	Not Applicable	Component	Pass	Fail	Not Applicable
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Component	Pass	Fail	Not Applicable	Component	Pass	Fail	Not Applicable
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer and Controlled-Steer Axle	✓		
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment	✓						

NOTES:

Component	Pass	Fail	Not Applicable	Component	Pass	Fail	Not Applicable
3H.1. Hydraulic System Components			✓	3H.13. Disc Brake System Components			✓
3H.2. Brake Pedal/Actuator			✓	3H.14. Mechanical Parking Brake			✓
3H.3. Vacuum Assist (Boost) System			✓	3H.15. Spring-Applied Air-Released Parking Brake			✓
3H.4. Hydraulic Assist (Boost) System			✓	3H.16. Spring-Applied Hydraulic-Released Parking Brake			✓
3H.5. Air Assist (Boost) System			✓	3H.17. Anti-Lock Brake System (ABS)			✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.18. Stability Control System			✓
3H.11. Brake System Indicator Lamps			✓	3H.19. Brake Performance			✓
3H.12. Drum Brake System Components			✓				

NOTES:

Component	Pass	Fail	Not Applicable	Component	Pass	Fail	Not Applicable
3A.1. Air Compressor	✓			3A.13. Air System Components	✓		
3A.2. Air Supply System	✓			3A.14. Brake Chamber	✓		
3A.4. Air Tank	✓			3A.15. Drum Brake System Components	✓		
3A.5. Air Tank Check Valves	✓			3A.16. S-Cam Drum Brake System	✓		
3A.6. Brake Pedal/Actuator	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.7. Throttle Valve and Trailer Hand Valve	✓			3A.18. Disc Brake System Components			✓
3A.8. Brake Valves & Controls	✓			3A.19. Anti-Lock Brake System (ABS)	✓		
3A.9. Proportioning, Inversion or Modulation Valve	✓			3A.21. Stability Control System			✓
3A.10. Towing Vehicle (Tractor) Protection System	✓			3A.22. Brake Performance	✓		

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Inspection Item	Pass	Fail	Not Applicable
3A.11. Parking Brake & Emergency Application	☒		

NOTES:

Inspection Item	Pass	Fail	Not Applicable
4.1. Steering Control and Linkage	☒		
4.2. Power Steering System (Hydraulic and Electric)	☒		
4.3. Steering Operation (Active Steer Axle)	☒		
4.4. Kingpin	☒		
4.5. Self-Steer and Controlled-Steer Axle	☒		

NOTES:

Inspection Item	Pass	Fail	Not Applicable
5.1. Fire Extinguisher	☒		
5.2. Hazard Warning Kit	☒		
5.3. Hgm	☒		
5.4. Speedometer	☒		
5.5. Odometer	☒		
5.7. Windshield Wiper/Washer	☒		
5.8. Heater & Windshield Defroster	☒		
5.9. Fuel-Burning Auxiliary Heater	☒		
5.10. Chain/Headache* Rack			☒
5.11. Auxiliary Controls and Devices	☒		
5.12. Auxiliary Drive Controls			☒

NOTES:

Inspection Item	Pass	Fail	Not Applicable
6.1. Required Lamps	☒		
6.2. Reflex Reflector	☒		
6.3. Retro-Reflective Marking	☒		
6.4. Instrument Panel Lamps	☒		
6.5. Headlamp Aim	☒		

NOTES:

Inspection Item	Pass	Fail	Not Applicable
7.1. Wiring	☒		
7.2. Battery	☒		
7.3. Trailer Cord (output to towed vehicle)			☒

NOTES:

Inspection Item	Pass	Fail	Not Applicable
8.1. Hood or Engine Enclosure	☒		
8.2. TR Cab	☒		
8.3. Air-Suspended Cab	☒		
8.4. Cab and Passenger-Vehicle Body	☒		
8.5. Cargo Body	☒		
8.6. Frame, Rails & Mounts	☒		
8.7. Utilized Body Elements	☒		
8.8. Cab or Cargo Door	☒		
8.9. Cargo Tank or Vessel	☒		
8.10. Body, Device or Equipment Attached or Mounted to the	☒		
8.12. Bumper	☒		
8.13. Windshield	☒		
8.14. Side Windows	☒		
8.15. Rear Window	☒		
8.16. Interior Sun Visor	☒		
8.17. Exterior Windshield Sun Visor	☒		
8.18. Rear-View Mirror	☒		
8.19. Seat	☒		
8.20. Seat Belt/Occupant Restraint	☒		
8.21. Fender/Mud Flap	☒		

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Vehicle									
8.11. Refrigeration/Heater Unit Fuel System (Roof or Auxiliary Power Unit (APU))				✓	8.24. Aerodynamic Device & Attachment			✓	

NOTES:

9.1. Tire Tread Depth	✓			9.7. Wheel/Rim (Applies to all wheel types)	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Dismountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts and Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

10.1. Hitch Assembly, Structure & Attaching Components			✓	10.5. Roll-Coupling Hitch			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.6. Automated Coupling Device			✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.7. Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓

NOTES:

The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #8254826) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.			
Date of Inspection 2028/05/01	Technician Number A2967	Facility Number 21721	Signature 
I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			Date (Year/Month/Day) 2028/05/01 Customer Signature 