


CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act


PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:		
GVW:	46500 kg	Brake Type:	Air	
Owner Name:	GN MOTORS LTD			
Address:	6520 174 AVE NW			
City:	EDMONTON	Province:	AB	Postal Code: T5Y3R2
Telephone Number:	(780) 993-8081			
Vehicle Identification Number:	5KJJAECVX5PN84494			
Make:	Western Star	Model:	Conventional	
Year:	2005	Unit Number:		
Odometer:	683473 KM	Licence Plate Number:	31P399	Province: AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
North Truck and Trailer Repair Ltd.	19938
Inspection Technician Name:	Technician Number:
Harman Dhillon	C6493
Inspection Technician Signature:	
Inspection Date:	2026/06/03

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Truck										46500 kg									
Vehicle information																			
VIN		5	K	J	J	A	E	C	V	X	5	P	N	8	4	4	9	4	
Unit Number				Year				Make				Model				Odometer			
				2005				Western Star				Conventional				683,473			
Registered Owner's Name																Plate Number			
GN MOTORS LTD																31P399			
Address												Postal Code				Phone Number			
6520 174 AVE NW												T5Y3R2				(780) 993-8081			
Drum Brakes: A-Full Inspection with Drum Removed Disc Brakes:																			

		LEFT		FRONT		RIGHT			
100 psi	14 mm	352.16	mm	Drums/Rotors		352.09	mm	100 psi	14 mm
		13	mm	Lining/Pads		15	mm		
		38	mm	Push Rod Travel		38	mm		
100 psi	17 mm	428.47	mm	Drums/Rotors		429.54	mm	100 psi	160 psi
		15	mm	Lining/Pads		17	mm		
		36	mm	Push Rod Travel		36	mm		
100 psi	17 mm	426.70	mm	Drums/Rotors		420.87	mm	100 psi	100 psi
		11	mm	Lining/Pads		10	mm		
		36	mm	Push Rod Travel		36	mm		
psi	mm	mm		Drums/Rotors		mm		psi	psi
		mm		Lining/Pads		mm			
		mm		Push Rod Travel		mm			
psi	mm	mm		Drums/Rotors		mm		psi	psi
		mm		Lining/Pads		mm			
		mm		Push Rod Travel		mm			
psi	mm	mm		Drums/Rotors		mm		psi	psi
		mm		Lining/Pads		mm			
		mm		Push Rod Travel		mm			

Park Brake Lining		Left	N/A	mm	Right	N/A	mm	Trans	N/A	mm
Wheel Torque Checked		☒	Inner	N/A	ft lbs	Outer	500	ft lbs		

VSSRQI2018

P=PASS F=FAIL NA=Not Applicable

Page 1 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR

Section 1 - Power Train							
Component	P	F	NA	Component	P	F	NA
1.1. Accelerator Pedal/Throttle Actuator	✓			1.2. Engine Start Safety Feature			
1.2. Exhaust System	✓			1.3. Cruise/Preclutch Inhibitor	✓		
1.3. Emission Control Systems and Devices	✓			1.10. Engine or Accessory Drive Belt	✓		
1.4. Drive Shaft	✓			1.11. Hybrid Electric Vehicle & Electric Vehicle Power Train System			✓
1.5. Clutch and Clutch Pedal	✓			1.12. Gasoline or Diesel Fuel System	✓		
1.6. Engine/Transmission Mount	✓			1.13. Pressurized or Liquefied Fuel System (LPG, CNG, & LNG)	✓		
1.7. Engine/Shut Down	✓			* SEE APPENDIX A*			

NOTES:
REPLACED CLUTCH BRAKE

APPENDIX "A"							
Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System				A.3. Liquefied Natural Gas (LNG) Fuel System			
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension							
Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension			✓
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer and Controlled-Steer Axle	✓		
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment	✓						

NOTES:

Section 3H - Hydraulic Brakes							
Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components	✓			3H.14. Line Brake System Components	✓		
3H.2. Brake Pedal/Actuator	✓			3H.14. Mechanical Parking Brake	✓		
3H.3. Vacuum Assist (Boost) System	✓			3H.15. Spring Applied, Air Released Parking Brake	✓		
3H.4. Hydraulic Assist (Boost) System	✓			3H.15. Spring Applied Hydraulic Released Parking Brake	✓		
3H.5. Air Assist (Boost) System	✓			3H.17. Anti-Lock Brake System (ABS)	✓		
3H.6. Air-Over-Hydraulic Brake System	✓			3H.18. Stability Control System	✓		
3H.11. Brake System Indicator Lamps	✓			3H.19. Brake Performance	✓		
3H.12. Drum Brake System Components	✓						

NOTES:

Section 3A - Air Brakes							
Component	P	F	NA	Component	P	F	NA
3A.1. Air Compressor	✓			3A.13. Air System Components	✓		
3A.2. Air Supply System	✓			3A.14. Brake Chamber	✓		
3A.4. Air Line	✓			3A.15. Drum Brake System Components	✓		
3A.5. Air Tank Check Valves	✓			3A.16. S-Cam Drum Brake System	✓		
3A.6. Brake Pedal/Actuator	✓			3A.17. Brake Shoe Travel (Wedge Brakes)	✓		
3A.7. Tractor Valve and Trailer Hand Valve	✓			3A.18. Disc Brake System Components	✓		
3A.8. Brake Valves & Controls	✓			3A.19. Anti-Lock Brake System (ABS)	✓		
3A.9. Proportional, Inversion or Modulation Valve	✓			3A.21. Stability Control System	✓		
3A.10. Towing Vehicle (Tractor) Protection System	✓			3A.23. Brake Lockup	✓		

VSSROI2015

P=PASS F=FAIL NA=Not Applicable

Page 2 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR

Section 3A - Air Brakes							
Component	P	F	NA	Component	P	F	NA
3A.11 Parking Brake & Emergency Application	✓						

NOTES:
STEERING AXLE D/S BRAKE CHAMBER HOSE RUBBED NEEDS TO BE REPLACED - REPLACED
DIFF LOCK AIR LEAK WHEN APPLIED - REPAIRED
5TH WHEEL CYLINDER AIR LEAK WHEN APPLIED - REPAIRED

Section 4 - Steering							
Component	P	F	NA	Component	P	F	NA
4.1 Steering Control and Linkage	✓			4.4 Kingpin			
4.2 Power Steering System (Hydraulic and Electric)	✓			4.6 Self-Steer and Controlled-Steer Axle	✓		
4.3 Steering Operation (Active Steer Axle)	✓						

NOTES:
DRAG LINK WORN - REPLACED

Section 5 - Instruments and Auxiliary Equipment							
Component	P	F	NA	Component	P	F	NA
5.1 Fire Extinguisher	✓			5.8 Heater & Windshield Defroster	✓		
5.2 Hazard Warning Kit	✓			5.9 Flash-Burning Auxiliary Lights			✓
5.3 Horn	✓			5.10 Chain/Heapsche's Rack			✓
5.5 Speedometer	✓			5.11 Auxiliary Controls and Devices			✓
5.6 Odometer	✓			5.12 Auxiliary Drive Controls			✓
5.7 Windshield Wiper/Washer	✓						

NOTES:
WASHER FLUID NOT WORKING - REPAIRED

Section 6 - Lamps							
Component	P	F	NA	Component	P	F	NA
6.1 Hazard Lamps	✓			6.4 Instrument Panel Lamps	✓		
6.2 Reflex Reflector	✓			6.5 Headlamp Aim	✓		
6.3 Retro-Reflective Marking	✓						

NOTES:
SOME MARKER LIGHTS NOT WORKING FRONT ORANGE AND REAR RED - REPAIRED
CAB REFLECTIVE TAPE WORN - INSTALLED
BACK UP LAMPS NOT WORKING - REPAIRED

Section 7 - Electrical System							
Component	P	F	NA	Component	P	F	NA
7.1 Wiring	✓			7.3 Trailer Cord (output to braked vehicle)	✓		
7.2 Battery	✓						

NOTES:

Section 8 - Body							
Component	P	F	NA	Component	P	F	NA
8.1 Hood or Engine Enclosure	✓			8.12 Bumper	✓		
8.2 Tilt Cab	✓			8.13 Windshield	✓		
8.3 Air-Suspended Cab	✓			8.14 Side Windows	✓		
8.4 Cab and Passenger-Vehicle Body	✓			8.15 Rear Window			✓
8.5 Cargo Body	✓			8.16 Interior Sun Visor	✓		
8.6 Frame, Rails & Mounts	✓			8.17 Exterior Windshield Sun Visor	✓		
8.7 Unfitted Body Elements	✓			8.18 Rear View Mirror	✓		

VSSROI2013

P=PASS F=FAIL NA=Not Applicable

Page 3 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR

Section 8 - Body							
Component	P	F	NA	Component	P	F	NA
8.8. Cab or Cargo Door	✓			8.19. Seat	✓		
8.9. Cargo Tank or Vessel			✓	8.20. Seat Belt/Occupant Restraint	✓		
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.21. Engine/Mud Flap	✓		
8.11. Refrigeration/Heater Unit Fuel System (Heater or Auxiliary Power Unit (APU))			✓	8.24. Aerodynamic Device & Attachment	✓		

NOTES:

Section 9 - Tires and Wheels							
Component	P	F	NA	Component	P	F	NA
9.1. Tread Depth	✓			9.2. Wheel/Steer (Applies to all wheel types)	✓		
9.2. Tire Tread Condition	✓			9.3. Mud-Flap/Wheel/Flym	✓		
9.3. Tire Slop/and Manufacturer Markings	✓			9.9. Spoke/Wheel/Dismountable Rim Systems	✓		
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts and Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:
ALL 8 TIRES REPLACED

Section 10 - Couplers and Hitches							
Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.5. Roll-Coupling Hitch	✓		
10.2. Secondary Attachment (Safety Chain or Cable)	✓			10.6. Automated Coupling Device	✓		
10.3. Pin/Key Hook, Pin Hitch, or Coupler Hitch	✓			10.7. Fifth Wheel Coupler	✓		
10.4. Ball Type Hitch	✓			10.8. Osculating Fifth Wheel Coupler	✓		

NOTES:
FIFTH WHEEL PLATE FRONT R/S CRACKED NEEDS WELDING - WELDED

Certification			
The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #8771210) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 21/2006 and the applicable Inspection Manual.			
Date of Inspection 2026/06/03	Technician Number C6493	Facility Number 19938	Signature 
Customer Acknowledgement			
I understand that a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			Date (Year/Month/Day) 2026/06/03
			Customer Signature

YSSROI2018

P=PASS F=FAIL NA=Not Applicable

Page 4 of 4

