

G29-2



CV8781297



80087800008781297

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act


PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	63500 kg	Brake Type:	Air
Owner Name:	1992549 ALBERTA LTD O/A L S CARRIERS		
Address:	451 42 AVE NW		
City:	EDMONTON	Province:	AB
		Postal Code:	T6T2G1
Telephone Number:	(587) 591-3231		
Vehicle Identification Number:	1XKDDDB0X76R986196		
Make:	Kenworth	Model:	Construct
Year:	2006	Unit Number:	
Odometer:	456692 KM	Licence Plate Number:	46P469
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Fast Tire & Repair Service Ltd.	21106
Inspection Technician Name:	Technician Number:
Anit Kumar	B1920
Inspection Technician Signature:	
Inspection Date:	2026/06/28