



CERTIFICATE NUMBER
**Commercial Vehicle Inspection Certificate
Traffic Safety Act**
**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	46500 kg	Brake Type:	Air
Owner Name:	MASI TRANSPORT LTD		
Address:	1924 GLENMOUNT DR SW		
City:	CALGARY	Province:	AB
		Postal Code:	T3E-4B6
Telephone Number:	(403) 998-5112		
Vehicle Identification Number:	4V4NC9EH6MN284974		
Make:	Volvo	Model:	VN
Year:	2021	Unit Number:	437
Odometer:	797307 KM	Licence Plate Number:	0GC114
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE
PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Masi Trailer Repair Ltd	21676
Inspection Technician Name:	Technician Number:
Rodrigo Martinez	B7337
Inspection Technician Signature:	
Inspection Date:	2026/06/12