



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	54300 kg	Brake Type:	Air
Owner Name:	ATLAS LAND SERVICES		
Address:	90 TUSCANY SUMMIT GREEN NW		
City:	CALGARY	Province:	AB
		Postal Code:	T3L 0B8
Telephone Number:	(403) 483-7706		
Vehicle Identification Number:	2FZHAZCVX7AY89306		
Make:	Sterling	Model:	Sterling
Year:	2007	Unit Number:	T07
Odometer:	641228 KM	Licence Plate Number:	76N300
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
WILLY HEAVY EQUIPMENT & AUTO REPAIR INC	21977
Inspection Technician Name:	Technician Number:
William Zuwe	C2668
Inspection Technician Signature:	
Inspection Date:	2026/05/04

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle Truck										Gross Vehicle Weight registered 54300 kg									
Vehicle Information																			
VIN	2	F	Z	H	A	Z	C	V	X	7	A	Y	8	9	3	0	6		
Unit Number T07				Year 2007				Make Sterling				Model Sterling				Odometer 641,228			
Registered Owner's Name ATLAS LAND SERVICES																Plate Number 76N300			
Address 90 TUSCANY SUMMIT GREEN NW												Postal Code T3L 0B8				Phone Number (403) 483-7706			

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		<u>LEFT</u>		<u>FRONT</u>		<u>RIGHT</u>			
100 psi 8 mm		421.96 mm	mm	Drums/Rotors	421.94 mm	mm	96 psi 7 mm		
		5 mm	mm	Linings/Pads	5 mm	mm			
		38 mm	mm	Push Rod Travel	38 mm	mm			
89 psi 15 mm	90 psi 19 mm	421.92 mm	mm	Drums/Rotors	421.86 mm	mm	100 psi 15 mm	88 psi 15 mm	
		5 mm	mm	Linings/Pads	6 mm	mm			
		38 mm	mm	Push Rod Travel	38 mm	mm			
100 psi 20 mm	102 psi 20 mm	421.90 mm	mm	Drums/Rotors	421.79 mm	mm	98 psi 20 mm	102 psi 19 mm	
		5 mm	mm	Linings/Pads	5 mm	mm			
		38 mm	mm	Push Rod Travel	38 mm	mm			
psi mm	psi mm	mm	mm	Drums/Rotors	mm	mm	psi mm	psi mm	
		mm	mm	Linings/Pads	mm	mm			
		mm	mm	Push Rod Travel	mm	mm			
psi mm	psi mm	mm	mm	Drums/Rotors	mm	mm	psi mm	psi mm	
		mm	mm	Linings/Pads	mm	mm			
		mm	mm	Push Rod Travel	mm	mm			
psi mm	psi mm	mm	mm	Drums/Rotors	mm	mm	psi mm	psi mm	
		mm	mm	Linings/Pads	mm	mm			
		mm	mm	Push Rod Travel	mm	mm			

Park Brake Lining Left NA mm Right NA mm Trans NA mm

Wheel Torque Checked ☒ Inner NA ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.1. Accelerator Pedal/Throttle Actuator	✓			1.8. Engine Start Safety Feature	✓		
1.2. Exhaust System	✓			1.9. Gear Position Indicator	✓		
1.3. Emission Control Systems and Devices	✓			1.10. Engine or Accessory Drive Belt	✓		
1.4. Drive Shaft	✓			1.11. Hybrid Electric Vehicle & Electric Vehicle Power Train System			✓
1.5. Clutch and Clutch Pedal	✓			1.12. Gasoline or Diesel Fuel System	✓		
1.6. Engine/Transmission Mount	✓			1.13. Pressurized or Liquefied Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓
1.7. Engine/Shut Down	✓						

NOTES:

STEADY BEARING WORN OUT
#1 AND #2 U-JOINT AFTER TRANSMISSION CAPS BROKEN
FRONT ENGINE MOUNTS WORN
REAR ENGINE MOUNTS WORN

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

=ALL REPAIRS HAVE BEEN CORRECTED=

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer and Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment	✓						

NOTES:

TORQUE ROD ABOVE #1 DIFF WORN OUT
ALL DRIVE AXLE SPRING BUSHINGS WORN OUT
STEER AXLE SPRING REAR LOWER BUSHINGS WORN OUT
DRIVE AXLE SHOCKS LEAKING

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.13. Disc Brake System Components			✓
3H.2. Brake Pedal/Actuator			✓	3H.14. Mechanical Parking Brake			✓
3H.3. Vacuum Assist (Boost) System			✓	3H.15. Spring-Applied Air-Released Parking Brake			✓
3H.4. Hydraulic Assist (Boost) System			✓	3H.16. Spring-Applied Hydraulic-Released Parking Brake			✓
3H.5. Air Assist (Boost) System			✓	3H.17. Anti-Lock Brake System (ABS)			✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.18. Stability Control System			✓
3H.11. Brake System Indicator Lamps			✓	3H.19. Brake Performance			✓
3H.12. Drum Brake System Components			✓				

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.1. Air Compressor	✓			3A.13. Air System Components	✓		
3A.2. Air Supply System	✓			3A.14. Brake Chamber	✓		
3A.4. Air Tank	✓			3A.15. Drum Brake System Components	✓		
3A.5. Air Tank Check Valves	✓			3A.16. S-Cam Drum Brake System	✓		

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.6. Brake Pedal/Actuator	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.7. Treadle Valve and Trailer Hand Valve	✓			3A.18. Disc Brake System Components			✓
3A.8. Brake Valves & Controls	✓			3A.19. Anti-Lock Brake System (ABS)	✓		
3A.9. Proportioning, Inversion or Modulation Valve	✓			3A.21. Stability Control System	✓		
3A.10. Towing Vehicle (Tractor) Protection System	✓			3A.23. Brake Performance	✓		
3A.11. Parking Brake & Emergency Application	✓						

NOTES:

REPLACE ALL 4 DRIVE AXLE BRAKE SHOES AND DRUMS
REPLACE BOTH STEER AXLE BRAKE SHOES AND DRUMS
REPLACE DRIVE AXLE ABS SENSORS
CHECK UNIT FOR AIR LEAKS

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control and Linkage	✓			4.4. Kingpin	✓		
4.2. Power Steering System (Hydraulic and Electric)	✓			4.5. Self-Steer and Controlled-Steer Axle			✓
4.3. Steering Operation (Active Steer Axle)	✓						

NOTES:

STEERING BOX INPUT SEAL LEAKING

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher	✓			5.8. Heater & Windshield Defroster	✓		
5.2. Hazard Warning Kit	✓			5.9. Fuel-Burning Auxiliary Heater			✓
5.3. Horn	✓			5.10. Chain/"Headache" Rack			✓
5.5. Speedometer	✓			5.11. Auxiliary Controls and Devices	✓		
5.6. Odometer	✓			5.12. Auxiliary Drive Controls	✓		
5.7. Windshield Wiper/Washer	✓						

NOTES:

WASHER RESERVOIR CAP MISSING

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.4. Instrument Panel Lamps	✓		
6.2. Reflex Reflector			✓	6.5. Headlamp Aim	✓		
6.3. Retro-Reflective Marking	✓						

NOTES:

HEAD LAMP ASSEMBLY BACK COVER BROKEN
REPAIR NON-OPERATIVE MARKER LIGHTS

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery	✓						

NOTES:

BATTERIES TERMINAL CORRODED

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.1. Hood or Engine Enclosure	✓			8.12. Bumper	✓		
8.2. Tilt Cab			✓	8.13. Windshield	✓		
8.3. Air-Suspended Cab	✓			8.14. Side Windows	✓		

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 8 - Body								
Component	P	F	NA	Component	P	F	NA	
8.4. Cab and Passenger-Vehicle Body	✓			8.15. Rear Window	✓			
8.5. Cargo Body	✓			8.16. Interior Sun Visor	✓			
8.6. Frame, Rails & Mounts	✓			8.17. Exterior Windshield Sun Visor	✓			
8.7. Unitized Body Elements	✓			8.18. Rear-View Mirror			✓	
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.19. Seat	✓			
8.8. Cab or Cargo Door	✓			8.20. Seat Belt/Occupant Restraint	✓			
8.11. Refrigeration/Heater Unit Fuel System (Reefer or Auxiliary Power Unit (APU))			✓	8.21. Fender/Mud Flap	✓			
8.9. Cargo Tank or Vessel	✓			8.24. Aerodynamic Device & Attachment			✓	

NOTES:

BOTH CAB SHOCKS LEAKING
REPLACE WINDSHIELD
TRUCK TARP RIPPED
WELD MULTIPLE CRACKS AT DUMP BOX TAILGATE

Section 9 - Tires and Wheels								
Component	P	F	NA	Component	P	F	NA	
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim (Applies to all wheel types)	✓			
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓	
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓	
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓			
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts and Studs)	✓			
9.6. Wheel Bearing	✓							

NOTES:

ADJUST TIRES PRESSURE

Section 10 - Couplers and Hitches								
Component	P	F	NA	Component	P	F	NA	
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.5. Roll-Coupling Hitch			✓	
10.2. Secondary Attachment (Safety Chain or Cable)	✓			10.6. Automated Coupling Device			✓	
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch	✓			10.7. Fifth Wheel Coupler			✓	
10.4. Ball Type Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓	

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #8458901)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/05/04	C2668	21977	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/05/04

Customer Signature