



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	MJB Enterprises Ltd.		
Address:	601 - 17th St. SW		
City:	Medicine Hat	Province:	AB
		Postal Code:	T1A4X6
Telephone Number:	(403) 527-3600		
Vehicle Identification Number:	2K9LF35084L052164		
Make:	K-Line	Model:	21
Year:	2004	Unit Number:	60-B
Odometer:	KM	Licence Plate Number:	W49134
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Hydraco Industries Ltd.	10779
Inspection Technician Name:	Technician Number:
Thomas McCuaig	B2201
Inspection Technician Signature:	<i>Tom McCuaig</i>
Inspection Date:	2026/07/30

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle Trailer										Gross Vehicle Weight registered kg									
Vehicle Information																			
VIN	2	K	9	L	F	3	5	0	8	4	L	0	5	2	1	6	4		
Unit Number 60-B			Year 2004			Make K-Line			Model 21			Odometer							
Registered Owner's Name MJB Enterprises Ltd.															Plate Number W49134				
Address 601 - 17th St. SW										Postal Code T1A4X6					Phone Number (403) 527-3600				

Drum Brakes: B-Wheel-on Full Inspection

Disc Brakes:

		<u>LEFT</u>		<u>FRONT</u>		<u>RIGHT</u>			
100 psi	100 psi	419.40 mm		Drums/Rotors		419.47 mm		100 psi	100 psi
15 mm	15 mm	17 mm		Linings/Pads		17 mm		17 mm	17 mm
		48 mm		Push Rod Travel		48 mm			
100 psi	100 psi	420.58 mm		Drums/Rotors		420.54 mm		100 psi	100 psi
11 mm	16 mm	17 mm		Linings/Pads		18 mm		12 mm	11 mm
		41 mm		Push Rod Travel		41 mm			
100 psi	100 psi	419.26 mm		Drums/Rotors		419.14 mm		100 psi	100 psi
13 mm	13 mm	16 mm		Linings/Pads		17 mm		9 mm	12 mm
		41 mm		Push Rod Travel		41 mm			
psi	psi	mm		Drums/Rotors		mm		psi	psi
mm	mm	mm		Linings/Pads		mm		mm	mm
		mm		Push Rod Travel		mm			
psi	psi	mm		Drums/Rotors		mm		psi	psi
mm	mm	mm		Linings/Pads		mm		mm	mm
		mm		Push Rod Travel		mm			
psi	psi	mm		Drums/Rotors		mm		psi	psi
mm	mm	mm		Linings/Pads		mm		mm	mm
		mm		Push Rod Travel		mm			

Park Brake Lining Left NA mm Right NA mm Trans NA mm
Wheel Torque Checked ☐ Inner _____ ft lbs Outer _____ ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment			✓				

NOTES:

AXLE 2 LH UPPER AIRBAG MOUNTING PLATE RUST JACKED/WORN OUT-REPLACED
AXLE 3 UPPER AIRBAG MOUNTING PLATES STARTING TO RUST JACK-MONITOR
AXLES 1,2 AND 3 PIVOT BUSHING WASHERS WORN-MONITOR

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓		
A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓
A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓		
A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓
A.14. Brake Chamber	✓			3A.23. Brake Performance	✓		
A.15. Drum Brake System Components	✓						

NOTES:

AXLE 3 LH BRAKE CHAMBER DUST PLUG DAMAGED-REPLACED
AXLE 1 LH AND AXLE 2 LH BRAKES HAVE MOUSE NESTS-CLEANED OUT
AXLE 3 LH BRAKE OUT OF ADJUSTMENT, STROKES VARY 3/8"FROM SIDE TO SIDE-REPAIRED
ADJUSTED ALL BRAKES

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4. Kingpin			✓				

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

RH FRONT WIDE LOAD ARM AMBER LIGHT INOPERATIVE-REPAIRED

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements			✓	8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door			✓	8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)	✓		

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

AXLE 3 LH WHEEL SEAL SWEATING-MONITOR

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler	✓		
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			
10.5. Roll-Coupling Hitch			✓				

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8676954) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/07/30	B2201	10779	<i>Tom McGraw</i>

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.	Date (Year/Month/Day) 2026/07/30
	Customer Signature