



CERTIFICATE NUMBER
**Commercial Vehicle Inspection Certificate
Traffic Safety Act**
**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	MJB Enterprises Ltd.		
Address:	601-17th St. SW		
City:	Medicine Hat	Province:	AB
		Postal Code:	T1A4X6
Telephone Number:	(403) 527-3600		
Vehicle Identification Number:	2C9BSR3W5LM183243		
Make:	Cross	Model:	Tridem Cross
Year:	2020	Unit Number:	25D
Odometer:	KM	Licence Plate Number:	6GF101
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE
PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Hydraco Industries Ltd.	10779
Inspection Technician Name:	Technician Number:
Thomas McCuaig	B2201
Inspection Technician Signature:	
Inspection Date:	2026/09/03

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered											
Trailer										kg											
Vehicle Information																					
VIN	2	C	9	B	S	R	3	W	5	L	M	1	8	3	2	4	3				
Unit Number			Year			Make			Model			Odometer									
25D			2020			Cross			Tridem Cross												
Registered Owner's Name																	Plate Number				
MJB Enterprises Ltd.																	6GF101				
Address												Postal Code				Phone Number					
601-17th St. SW												T1A4X6				(403) 527-3600					

Drum Brakes: B-Wheel-on Full Inspection

Disc Brakes:

		<u>LEFT</u>		<u>FRONT</u>		<u>RIGHT</u>			
100 psi	100 psi	421.30 mm	Drums/Rotors	421.25 mm		100 psi	100 psi		
7 mm	7 mm	14 mm	Linings/Pads	14 mm		6 mm	9 mm		
		44 mm	Push Rod Travel	44 mm					
100 psi	100 psi	421.66 mm	Drums/Rotors	421.84 mm		100 psi	100 psi		
11 mm	10 mm	14 mm	Linings/Pads	14 mm		10 mm	11 mm		
		44 mm	Push Rod Travel	44 mm					
100 psi	100 psi	421.82 mm	Drums/Rotors	421.51 mm		100 psi	100 psi		
10 mm	10 mm	14 mm	Linings/Pads	14 mm		5 mm	6 mm		
		47 mm	Push Rod Travel	47 mm					
psi	psi	mm	Drums/Rotors	mm		psi	psi		
mm	mm	mm	Linings/Pads	mm		mm	mm		
		mm	Push Rod Travel	mm					
psi	psi	mm	Drums/Rotors	mm		psi	psi		
mm	mm	mm	Linings/Pads	mm		mm	mm		
		mm	Push Rod Travel	mm					
psi	psi	mm	Drums/Rotors	mm		psi	psi		
mm	mm	mm	Linings/Pads	mm		mm	mm		
		mm	Push Rod Travel	mm					
Park Brake Lining Left <u>NA</u> mm Right <u>NA</u> mm Trans <u>NA</u> mm Wheel Torque Checked ☒ Inner <u>NA</u> ft lbs Outer <u>500</u> ft lbs									

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment			✓				

NOTES:

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓		
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓		
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance	✓		
3A.15. Drum Brake System Components	✓						

NOTES:

FRONT AIR TANK DRAIN LEAKING-REPLACED
AXLE 3 LH BRAKE DUST SHIELD MISSING-INSTALLED

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin			✓				

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

2 REAR TRI-LIGHTS HAVE MORE THAN 1/2 OF LEDS INOPERATIVE-REPLACED

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door	✓			8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)			✓

NOTES:

CRACKS ON FRONT HOPPER BOTH SIDES-REPAIRED CRACKS

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

LOW TIRE PRESSURES-SET TO 100 PSI
AXLE 3 LH INNER TIRE WORN OUT-REPLACED
AXLE 1 RH INNER AND AXLE 3 RH TIRES WORN 5-6 MM LEFT-MONITOR
TORQUED WHEELS TO 500 FT LBS

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler	✓		
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8676978) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/09/03	B2201	10779	<i>Tom McGaughey</i>

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/09/03

Customer Signature