



**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

N02-1

Vehicle Type:	Truck	Seating Capacity:	
GVW:	54500 kg	Brake Type:	Air
Owner Name:	JOHANNA TRUCKING LTD		
Address:	PO BOX 57		
City:	BROOKS	Province:	AB
		Postal Code:	T0J0Z0
Telephone Number:	(403) 894-9472		
Vehicle Identification Number:	1XPTPPEXXFD271946		
Make:	Peterbilt	Model:	Conventional
Year:	2015	Unit Number:	T-1
Odometer:	745635 KM	Licence Plate Number:	A47867
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
TDM Hose & Hydraulics Ltd	21121
Inspection Technician Name:	Technician Number:
Tate Hemminger	D2155
Inspection Technician Signature:	
Inspection Date:	2026/09/18



COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Truck										54500 kg									
Vehicle Information																			
VIN	1	X	P	T	P	P	E	X	X	F	D	2	7	1	9	4	6		
Unit Number		Year		Make				Model				Odometer							
T-1		2015		Peterbilt				Conventional				745,635							
Registered Owner's Name														Plate Number					
JOHANNA TRUCKING LTD														A47867					
Address										Postal Code				Phone Number					
PO BOX 57										T0J0Z0				(403) 894-9472					

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		LEFT	FRONT	RIGHT		
100 psi	0.52 in	16.55 in	Drums/Rotors	16.55 in	100 psi	0.61 in
		0.75 in	Linings/Pads	0.73 in		
		NA in	Push Rod Travel	NA in		
100 psi	0.63 in	16.53 in	Drums/Rotors	16.54 in	100 psi	0.51 in
100 psi	0.61 in	0.74 in	Linings/Pads	0.71 in	100 psi	0.48 in
		NA in	Push Rod Travel	NA in		
100 psi	0.64 in	16.54 in	Drums/Rotors	16.54 in	100 psi	0.58 in
100 psi	0.65 in	0.72 in	Linings/Pads	0.56 in	100 psi	0.54 in
		NA in	Push Rod Travel	NA in		
100 psi	0.56 in	16.55 in	Drums/Rotors	16.56 in	100 psi	0.59 in
100 psi	0.63 in	0.66 in	Linings/Pads	0.71 in	100 psi	0.58 in
		NA in	Push Rod Travel	NA in		
psi	in	in	Drums/Rotors	in	psi	in
		in	Linings/Pads	in		
		in	Push Rod Travel	in		
psi	in	in	Drums/Rotors	in	psi	in
		in	Linings/Pads	in		
		in	Push Rod Travel	in		
Park Brake Lining Left NA in Right NA in Trans NA in						
Wheel Torque Checked ☒ Inner NA ft lbs Outer 500 ft lbs						

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 1 - Power Train								
Component	P	F	NA	Component	P	F	NA	
1.1. Accelerator Pedal/Throttle Actuator	✓			1.8. Engine Start Safety Feature	✓			
1.2. Exhaust System	✓			1.9. Gear Position Indicator	✓			
1.3. Emission Control Systems and Devices	✓			1.10. Engine or Accessory Drive Belt	✓			
1.4. Drive Shaft	✓			1.11. Hybrid Electric Vehicle & Electric Vehicle Power Train System			✓	
1.5. Clutch and Clutch Pedal	✓			1.12. Gasoline or Diesel Fuel System	✓			
1.6. Engine/Transmission Mount	✓			1.13. Pressurized or Liquefied Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓	
1.7. Engine/Shut Down	✓							

NOTES:

STEADY BEARING HAS PLAY. REPLACED. FAN BELT WORN. REPLACED. TRANSMISSION TEMP SENSOR, WIRING BROKEN. REPAIRED. FAN HUB LEAKING. REPLACED.

APPENDIX "A"								
Component	P	F	NA	Component	P	F	NA	
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓	
A.2. Compressed Natural Gas (CNG) Fuel System			✓					

NOTES:

Section 2 - Suspension								
Component	P	F	NA	Component	P	F	NA	
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓			
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer and Controlled-Steer Axle	✓			
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓			
2.4. Spring & Spring Attachment	✓							

NOTES:

AXLE 3 & 4 TRANSVERSE ARM BUSHINGS PUSHED OUT. REPAIRED. AXLE 3 PS SPRING ROLLER, BUSHING MISSING. REPLACED.

Section 3H - Hydraulic Brakes								
Component	P	F	NA	Component	P	F	NA	
3H.1. Hydraulic System Components			✓	3H.13. Disc Brake System Components			✓	
3H.2. Brake Pedal/Actuator			✓	3H.14. Mechanical Parking Brake			✓	
3H.3. Vacuum Assist (Boost) System			✓	3H.15. Spring-Applied Air-Released Parking Brake			✓	
3H.4. Hydraulic Assist (Boost) System			✓	3H.16. Spring-Applied Hydraulic-Released Parking Brake			✓	
3H.5. Air Assist (Boost) System			✓	3H.17. Anti-Lock Brake System (ABS)			✓	
3H.6. Air-Over-Hydraulic Brake System			✓	3H.18. Stability Control System			✓	
3H.11. Brake System Indicator Lamps			✓	3H.19. Brake Performance			✓	
3H.12. Drum Brake System Components			✓					

NOTES:

Section 3A - Air Brakes								
Component	P	F	NA	Component	P	F	NA	
3A.1. Air Compressor	✓			3A.13. Air System Components	✓			
3A.2. Air Supply System	✓			3A.14. Brake Chamber	✓			
3A.4. Air Tank	✓			3A.15. Drum Brake System Components	✓			
3A.5. Air Tank Check Valves	✓			3A.16. S-Cam Drum Brake System	✓			
3A.6. Brake Pedal/Actuator	✓			3A.17. Brake Shoe Travel (Wedge Brakes)	✓			
3A.7. Treadle Valve and Trailer Hand Valve	✓			3A.18. Disc Brake System Components			✓	
3A.8. Brake Valves & Controls	✓			3A.19. Anti-Lock Brake System (ABS)	✓			
3A.9. Proportioning, Inversion or Modulation Valve	✓			3A.21. Stability Control System	✓			
3A.10. Towing Vehicle (Tractor) Protection System	✓			3A.23. Brake Performance	✓			

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 3A - Air Brakes								
Component	P	F	NA	Component	P	F	NA	
3A.11. Parking Brake & Emergency Application	✓							

NOTES:

AXLE 3 & 4 ABS WIRING NEEDS TO BE TIED UP. REPAIRED. REPLACED AXLE 3 DS BRAKE POT SERVICE LINE. TIED UP AXLE 2 & 3 BRAKEPOT LINES. REPLACED AXLE 3 DS BRAKE POT PLUG.

Section 4 - Steering								
Component	P	F	NA	Component	P	F	NA	
4.1. Steering Control and Linkage	✓			4.4. Kingpin	✓			
4.2. Power Steering System (Hydraulic and Electric)	✓			4.5. Self-Steer and Controlled-Steer Axle	✓			
4.3. Steering Operation (Active Steer Axle)	✓							

NOTES:

DS TIE ROD HAS PLAY. REPLACED & ALIGNED AXLE 1.

Section 5 - Instruments and Auxiliary Equipment								
Component	P	F	NA	Component	P	F	NA	
5.1. Fire Extinguisher	✓			5.8. Heater & Windshield Defroster	✓			
5.2. Hazard Warning Kit	✓			5.9. Fuel-Burning Auxiliary Heater	✓			
5.3. Horn	✓			5.10. Chain/"Headache" Rack				✓
5.5. Speedometer	✓			5.11. Auxiliary Controls and Devices				✓
5.6. Odometer	✓			5.12. Auxiliary Drive Controls				✓
5.7. Windshield Wiper/Washer	✓							

NOTES:

Section 6 - Lamps								
Component	P	F	NA	Component	P	F	NA	
6.1. Required Lamps	✓			6.4. Instrument Panel Lamps	✓			
6.2. Reflex Reflector	✓			6.5. Headlamp Aim	✓			
6.3. Retro-Reflective Marking	✓							

NOTES:

DS REAR TAIL LIGHT NO SIGNAL. REPAIRED. DS HEADLIGHT CLEARANCE AMBER & SIGNAL INOP. REPLACED. PS BUMPER AMBER NO SIGNAL. REPAIRED. BOTH FENDER LIGHTS NO SIGNAL. REPLACED. PS HEADLIGHT NO SIGNAL. REPAIRED. PS MIRROR LIGHT NO SIGNAL. REPLACED. DS AIR CLEANER AMBER 1 INOP. REPLACED.

Section 7 - Electrical System								
Component	P	F	NA	Component	P	F	NA	
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓			
7.2. Battery	✓							

NOTES:

Section 8 - Body								
Component	P	F	NA	Component	P	F	NA	
8.1. Hood or Engine Enclosure	✓			8.12. Bumper	✓			
8.2. Tilt Cab			✓	8.13. Windshield	✓			
8.3. Air-Suspended Cab	✓			8.14. Side Windows	✓			
8.4. Cab and Passenger-Vehicle Body	✓			8.15. Rear Window				✓
8.5. Cargo Body	✓			8.16. Interior Sun Visor	✓			
8.6. Frame, Rails & Mounts	✓			8.17. Exterior Windshield Sun Visor	✓			
8.7. Unitized Body Elements	✓			8.18. Rear-View Mirror	✓			
8.8. Cab or Cargo Door	✓			8.19. Seat	✓			

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 8 - Body						
Component	P	F	NA	Component	P	F NA
8.9. Cargo Tank or Vessel			✓	8.20. Seat Belt/Occupant Restraint		
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.21. Fender/Mud Flap	✓	
8.11. Refrigeration/Heater Unit Fuel System (Reefer or Auxiliary Power Unit (APU))			✓	8.24. Aerodynamic Device & Attachment		✓

NOTES:

BOTH CAB AIRBAGS LEAKING. REPLACED. PS MIRROR & CONVEX MIRROR BROKEN. REPLACED.

Section 9 - Tires and Wheels						
Component	P	F	NA	Component	P	F NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim (Applies to all wheel types)	✓	
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim		✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System		✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓	
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts and Studs)	✓	
9.6. Wheel Bearing	✓					

NOTES:

ADJUSTED TIRE PSI. AXLE 3 DS INNER TIRE VALVE CAP MISSING. REPLACED. AXLE 4 PS OUTER TIRE VALVE CAP MISSING. REPLACED.

Section 10 - Couplers and Hitches						
Component	P	F	NA	Component	P	F NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.5. Roll-Coupling Hitch		✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.6. Automated Coupling Device		✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.7. Fifth Wheel Coupler	✓	
10.4. Ball Type Hitch			✓	10.8. Oscillating Fifth Wheel Coupler		✓

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #8761238)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection 2026/09/18	Technician Number D2155	Facility Number 21121	Signature 
---	-----------------------------------	---------------------------------	--

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/09/18

Customer Signature