

092-4



CV8341197



80087300008341197

CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Electric
Owner Name:	Mundo Underground Ltd.		
Address:	121-23045 Twp Rd 514		
City:	Sherwood Park	Province:	AB
		Postal Code:	T8B1K9
Telephone Number:	(780) 886-7715		
Vehicle Identification Number:	2DACC8378MT022726		
Make:	Double A	Model:	CT217-24
Year:	2021	Unit Number:	T10
Odometer:	KM	Licence Plate Number:	6GS570
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:		Facility Number:	
Ledon Mechanical Inc.		21816	
Inspection Technician Name:		Technician Number:	
Donald Sauvageau		B8009	
Inspection Technician Signature:			
Inspection Date:	2025/10/23		

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Trailer										kg									
Vehicle Information																			
VIN	2	D	A	C	C	8	3	7	8	M	T	0	2	2	7	2	6		
Unit Number T10				Year 2021				Make Double A				Model CT217-24				Odometer			
Registered Owner's Name Mundo Underground Ltd.															Plate Number 6GS570				
Address 121-23045 Twp Rd 514										Postal Code T8B1K9					Phone Number (780) 886-7715				

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		<u>LEFT</u>		<u>FRONT</u>		<u>RIGHT</u>			
NA psi	46 psi	305.29 mm		Drums/Rotors	305.29 mm	50 psi	NA psi		
NA mm	6 mm	6 mm		Linings/Pads	6 mm	7 mm	NA mm		
		NA mm		Push Rod Travel	NA mm				
NA psi	48 psi	305.35 mm		Drums/Rotors	305.24 mm	48 psi	NA psi		
NA mm	7 mm	5 mm		Linings/Pads	5 mm	7 mm	NA mm		
		NA mm		Push Rod Travel	NA mm				
NA psi	50 psi	305.35 mm		Drums/Rotors	305.48 mm	50 psi	NA psi		
NA mm	7 mm	5.5 mm		Linings/Pads	5 mm	7 mm	NA mm		
		NA mm		Push Rod Travel	NA mm				
psi	psi	mm		Drums/Rotors	mm	psi	psi		
mm	mm	mm		Linings/Pads	mm	mm	mm		
		mm		Push Rod Travel	mm				
psi	psi	mm		Drums/Rotors	mm	psi	psi		
mm	mm	mm		Linings/Pads	mm	mm	mm		
		mm		Push Rod Travel	mm				
psi	psi	mm		Drums/Rotors	mm	psi	psi		
mm	mm	mm		Linings/Pads	mm	mm	mm		
		mm		Push Rod Travel	mm				
Park Brake Lining		Left	NA mm	Right	NA mm	Trans	NA mm		
Wheel Torque Checked		✓	Inner	NA	ft lbs	Outer	110	ft lbs	

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System				✓ 1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments			✓	2.5. Air Suspension			✓
2.2. Axle Attaching & Tracking Components			✓	2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly			✓	2.7. Shock Absorber/Strut Assembly			✓
2.4. Spring & Spring Attachment			✓				

NOTES:

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System		✓	
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components		✓	
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance		✓	
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage			✓	3A.16. S-Cam Drum Brake System			✓
3A.4. Air Tank			✓	3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls			✓	3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application			✓	3A.20. Anti-Lock Brake System (ABS)			✓
3A.13. Air System Components			✓	3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber			✓	3A.23. Brake Performance			✓
3A.15. Drum Brake System Components			✓				

NOTES:

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin			✓				

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking			✓
6.2. Reflex Reflector	✓						

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)			✓
7.2. Battery	✓						

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body			✓	8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements			✓	8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door			✓	8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)			✓

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System			✓
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

Section 10 - Couplers and Hitches


Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)	✓			10.7. Fifth Wheel Coupler			✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch	✓			10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #8341197)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2025/10/23	B8009	21816	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2025/10/23

Customer Signature