


CERTIFICATE NUMBER

Salvage Vehicle Inspection Certificate Traffic Safety Act

C12-3

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:		Brake Type:	Air
Owner Name:	EXL AGGREGATE AND RENTALS LTD		
Address:	4120 41ST		
City:	DRAYTON VALLEY	Province:	AB
		Postal Code:	T7A0B4
Telephone Number:	(780) 898-0023		
Vehicle Identification Number:	1NPTX4TX8FD271343		
Make:	Peterbilt	Model:	Conventional
Year:	2015	Unit Number:	ST208
Odometer:	253833 KM	Licence Plate Number:	13P359
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Salvage Vehicle.

Structural Facility Name:	Facility Number:
Parts for Trucks, Inc.	16544
Structural Technician Name:	Technician Number:
David Martin	B2795
Structural Technician Signature	Inspection Date
<i>David Martin</i>	2026/10/09
Mechanical Facility Name:	Facility Number:
Parts for Trucks, Inc.	16544
Mechanical Technician Name:	Technician Number:
Nikola Milic	B7472
Mechanical Technician Signature	Inspection Date
<i>Nikola Milic</i>	2026/10/09

NOTICE TO VEHICLE OWNER

1. This inspection certificate expires after 14 days from the Inspection date. After 14 days, a complete re-inspection of the vehicle is required.
2. The original of this Certificate must be presented to an Alberta Registry Agent within 14 days; however, there is no requirement to register the vehicle when the certificate is presented.