



Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	LOWKEY TRANSPORT LTD		
Address:	SITE 32 COMP 25 RR 8 STN MAIN		
City:	LETHBRIDGE	Province:	AB
		Postal Code:	T1J4P4
Telephone Number:	(403) 382-0298		
Vehicle Identification Number:	1GRAA96203W063105		
Make:	Great Dane	Model:	7811 TZ-1A
Year:	2003	Unit Number:	LK48002
Odometer:	KM	Licence Plate Number:	4EY497
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
A.S.A.P Truck & Trailer Repairs Ltd.	13437
Inspection Technician Name:	Technician Number:
James Johnston	C9515
Inspection Technician Signature:	
Inspection Date:	2026/03/30

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered											
Trailer										kg											
Vehicle Information																					
VIN	1	G	R	A	A	9	6	2	0	3	W	0	6	3	1	0	5				
Unit Number				Year				Make				Model				Odometer					
LK48002				2003				Great Dane				7811 TZ-1A									
Registered Owner's Name																Plate Number					
LOWKEY TRANSPORT LTD																4EY497					
Address												Postal Code				Phone Number					
SITE 32 COMP 25 RR 8 STN MAIN												T1J4P4				(403) 382-0298					

Drum Brakes: B-Wheel-on Full Inspection

Disc Brakes:

		<u>LEFT</u>		<u>FRONT</u>		<u>RIGHT</u>			
100 psi	100 psi	16.525	in	Drums/Rotors	16.543	in		100 psi	100 psi
20/32 in	21/32 in	3/4	in	Linings/Pads	5/8	in		22/32 in	19/32 in
		1 1/4	in	Push Rod Travel	1 1/4	in			
100 psi	100 psi	16.500	in	Drums/Rotors	16.500	in		100 psi	100 psi
21/32 in	18/32 in	7/8	in	Linings/Pads	7/8	in		20/32 in	21/32 in
		1 1/4	in	Push Rod Travel	1 1/4	in			
psi	psi		in	Drums/Rotors		in		psi	psi
in	in		in	Linings/Pads		in		in	in
			in	Push Rod Travel		in			
psi	psi		in	Drums/Rotors		in		psi	psi
in	in		in	Linings/Pads		in		in	in
			in	Push Rod Travel		in			
psi	psi		in	Drums/Rotors		in		psi	psi
in	in		in	Linings/Pads		in		in	in
			in	Push Rod Travel		in			
psi	psi		in	Drums/Rotors		in		psi	psi
in	in		in	Linings/Pads		in		in	ir
			in	Push Rod Travel		in			

Park Brake Lining Left N/A in Right N/A in Trans N/A in
 Wheel Torque Checked ☒ Inner N/A ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train						
Component	P	F	NA	Component	P	F NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*		✓

NOTES:

APPENDIX "A"						
Component	P	F	NA	Component	P	F NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System		✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓			

NOTES:

Section 2 - Suspension						
Component	P	F	NA	Component	P	F NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓	
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle		✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓	
2.4. Spring & Spring Attachment			✓			

NOTES:

2.5 FL AIRBAG SHOWING CORDS/REPAIRS MADE

2.7 FR SHOCK LEAKING/REPAIRS MADE

Section 3H - Hydraulic Brakes						
Component	P	F	NA	Component	P	F NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System		✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components		✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components		✓
3H.8. Vacuum System			✓	3H.19. Brake Performance		✓
3H.9. Air-Boosted Trailer Brake System			✓			

NOTES:

Section 3A - Air Brakes						
Component	P	F	NA	Component	P	F NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓	
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)		✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components		✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓	
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)		✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance	✓	
3A.15. Drum Brake System Components	✓					

NOTES:

3A.14 FRONT AXLE BREAK PODS EMERGENCY SPRING BROKEN/REPAIRS MADE

3A.16 FR S CAM BUSHING OUT OF SPEC/REPAIRS MADE

3A.20 ABS NOT CYCLING/REPAIRS MADE

Section 4 - Steering						
Component	P	F	NA	Component	P	F NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle		✓
4.4. Kingpin			✓			

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

6.1 2 MARKER LIGHTS ON REAR ON TOP NOT OPERATIONAL /REPAIRS MADE

6.1 LICENCE PLATE LIGHT NOT OPERATIONAL/REPAIRS MADE

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System	✓		
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door	✓			8.23. Sliding Axle Assembly (Sliding Bogie)	✓		
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle			✓	8.25. Rear Impact Guard (RIG)	✓		

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

9.5 ALL HUBS CAPS LEAKING/REPAIRS MADE

9.6 BR WHEEL SEAL LEAKING/REPAIRS MADE

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler	✓		
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8698260) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/03/30	C9515	13437	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/03/30

Customer Signature