



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	46500 kg	Brake Type:	Air
Owner Name:	1183090 ALBERTA LTD		
Address:	80-4797 22 ST SE		
City:	CALGARY	Province:	AB
		Postal Code:	T2B0N8
Telephone Number:	(403) 998-5112		
Vehicle Identification Number:	4V4NC9EH6LN257806		
Make:	Volvo	Model:	VN
Year:	2020	Unit Number:	337
Odometer:	1013960 KM	Licence Plate Number:	OCF642
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
North Truck and Trailer Repair Ltd.	19938
Inspection Technician Name:	Technician Number:
Daljeet Dhillon	D1976
Inspection Technician Signature:	
Inspection Date:	2026/03/03



COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle	Truck		Gross Vehicle Weight registered	46500 kg	
Vehicle Information					
VIN	4 V 4 N C 9 E H 6 L N 2 5 7 8 0 6				
Unit Number	337	Year	2020	Make	Volvo
				Model	VN
				Odometer	1,013,960
Registered Owner's Name				Plate Number	
1163090 ALBERTA LTD				OCF642	
Address				Postal Code	
80-4797 22 ST SE				T2B0N8	
Phone Number				(403) 998-5112	
Drum Brakes: A-Full Inspection with Drum Removed					
Disc Brakes:					
LEFT FRONT RIGHT					
100 psi 421.00 mm Drums/Rotors 421.13 mm 100 psi					
15 mm 24 mm Linings/Pads 24 mm					
32 mm Push Rod Travel 32 mm					
100 psi 420.62 mm Drums/Rotors 420.37 mm 100 psi					
10 mm 22 mm Linings/Pads 23 mm					
44 mm Push Rod Travel 42 mm					
100 psi 428.37 mm Drums/Rotors 420.49 mm 100 psi					
18 mm 22 mm Linings/Pads 23 mm					
44 mm Push Rod Travel 40 mm					
Park Brake Lining Left N/A mm Right N/A mm Trans N/A mm					
Wheel Torque Checked ☒ Inner N/A ft lbs Outer 890 ft lbs					

VSSRO/2016

P=PASS F=FAIL NA=Not Applicable

Page 1 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 1 - Power Train							
Component	P	F	NA	Component	P	F	NA
1.1. Accelerator Pedal/Throttle Actuator	☒			1.8. Engine Start Safety Feature	☒		
1.2. Exhaust System	☒			1.9. Gear Position Indicator	☒		
1.3. Emission Control Systems and Devices	☒			1.10. Engine or Accessory Drive Belt	☒		
1.4. Drive Shaft	☒			1.11. Hybrid Electric Vehicle & Electric Vehicle Power Train System	☒		
1.5. Clutch and Clutch Pedal	☒			1.12. Gasoline or Diesel Fuel System	☒		
1.6. Engine/Turbocharger Mount	☒			1.13. Pressurized or Liquefied Fuel System (LPG, CNG, & LNG)	☒		
1.7. Engine/Shutdown	☒			*SEE APPENDIX A*			
NOTES:							
APPENDIX A							
Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System	☒			A.2. Compressed Natural Gas (CNG) Fuel System	☒		
NOTES:							
Section 2 - Suspension							
Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	☒			2.5. Air Suspension	☒		
2.2. Axle Assembling & Tracking Components	☒			2.6. Self-Steer and Controlled-Steer Axle	☒		
2.3. Axle & Axle Assembly	☒			2.7. Shock Absorber/Strut Assembly	☒		
2.4. Spring & Spring Attachment	☒						
NOTES:							
2ND AXLE D/W DEAR PAD BAD - REPLACED							
Section 3H - Hydraulic Brakes							
Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components	☒			3H.13. Disc Brake System Components	☒		
3H.2. Brake Pedal/Actuator	☒			3H.14. Mechanical Parking Brake	☒		
3H.3. Vacuum Assisted (Boost) System	☒			3H.15. Spring-Loaded Air-Released Parking Brake	☒		
3H.4. Hydraulic Assisted (Boost) System	☒			3H.16. Spring-Loaded Hydraulic Brake and Parking Brake	☒		
3H.5. Air Assisted (Boost) System	☒			3H.17. Anti-Lock Brake System (ABS)	☒		
3H.6. Air-Over-Hydraulic Brake System	☒			3H.18. Stability Control System	☒		
3H.11. Brake System Indicator Lamps	☒			3H.19. Brake Performance	☒		
3H.12. Drum Brake System Components	☒						
NOTES:							
Section 3A - Air Brakes							
Component	P	F	NA	Component	P	F	NA
3A.1. Air Compressor	☒			3A.13. Air System Components	☒		
3A.2. Air Supply System	☒			3A.14. Brake Chamber	☒		
3A.3. Air Tank	☒			3A.15. Drum Brake System Components	☒		
3A.4. Air Tank Check Valve	☒			3A.16. S-Cam Drum Brake System	☒		
3A.5. Air Tank Drain Valve	☒			3A.17. Brake Shoe Travel (Wedge Brakes)	☒		
3A.6. Brake Pedal/Actuator	☒			3A.18. Disc Brake System Components	☒		
3A.7. Treadle Valve and Trailer Hand Valve	☒			3A.19. Air-Lock Brake System (ALB)	☒		
3A.8. Brake Valves & Controls	☒			3A.21. Stability Control System	☒		
3A.9. Proportioning, Inversion or Modulator Valve	☒			3A.22. Brake Performance	☒		
3A.10. Trailing Vehicle (Tractor) Protection System	☒						
NOTES:							

VSSRO/2016

P=PASS F=FAIL NA=Not Applicable

Page 2 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 3A - Air Brakes							
Component	P	F	NA	Component	P	F	NA
3A.11. Parking Brake & Emergency Application	☒						
NOTES:							
Section 4 - Steering							
Component	P	F	NA	Component	P	F	NA
4.1. Steering Control and Linkage	☒			4.4. Knocks	☒		
4.2. Power Steering System (Hydraulic and Electric)	☒			4.5. Self-Steer and Controlled-Steer Axle	☒		
4.3. Steering Operation (Active Steer Axle)	☒						
NOTES:							
Section 5 - Instruments and Auxiliary Equipment							
Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher	☒			5.8. Heater & Windshield Defroster	☒		
5.2. Hazard Warning x4	☒			5.9. Fuel-Burning Auxiliary Heater	☒		
5.3. Horn	☒			5.10. Chassis/Tractor's Shock	☒		
5.5. Speedometer	☒			5.11. Auxiliary Controls and Devices	☒		
5.6. Odometer	☒			5.12. Auxiliary Drive Controls	☒		
5.7. Windshield Wiper/Washer	☒						
NOTES:							
Section 6 - Lamps							
Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	☒			6.4. Instrument Panel Lamps	☒		
6.2. Reflector Marking	☒			6.5. Headlamp Aim	☒		
6.3. Reflector Marking	☒						
NOTES:							
Section 7 - Electrical System							
Component	P	F	NA	Component	P	F	NA
7.1. Wiring	☒			7.2. Trailer Cord (connected to towed vehicle)	☒		
7.2. Battery	☒						
NOTES:							
Section 8 - Body							
Component	P	F	NA	Component	P	F	NA
8.1. Hood or Engine Enclosure	☒			8.12. Lumper	☒		
8.2. Top Cab	☒			8.13. Windshield	☒		
8.3. Air-Suspended Cab	☒			8.14. Side Windows	☒		
8.4. Cab and Passenger Vehicle Body	☒			8.15. Rear Windows	☒		
8.5. Cargo Body	☒			8.16. Interior Side View	☒		
8.6. Frame, Bump & Mounts	☒			8.17. Exterior Windshield Rank View	☒		
8.7. Mounted Body Elements	☒			8.18. Plate View Mirror	☒		
8.8. Cab or Cargo Door	☒			8.19. Seat	☒		
8.9. Cargo Tank or Vessel	☒			8.20. Seat Belt/Occupant Restraint	☒		
8.10. Other, Device or Equipment Attached or Mounted to the	☒			8.21. Frontal/Curtain Flap	☒		

VSSRO/2016

P=PASS F=FAIL NA=Not Applicable

Page 3 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 8 - Body							
Component	P	F	NA	Component	P	F	NA
8.1. The Load Capacity	☒			8.24. Aerodynamic Device & Attachment	☒		
8.2. The Load Condition	☒						
8.3. The Load and Manufacturer Markings	☒						
8.4. Tire Inflation Pressures	☒						
8.5. Wheel Hub	☒						
8.6. Wheel Bearing	☒						
NOTES:							
Section 9 - Couplers and Hitches							
Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	☒			10.6. Roll-Coupling Hitch	☒		
10.2. Secondary Attachment (Safety Chain or Cable)	☒			10.8. Automated Coupling Device	☒		
10.3. Pull Hook, Pin Hitch, or Coupler Hitch	☒			10.7. Fifth Wheel Coupler	☒		
10.4. Ball Type Hitch	☒			10.9. Oscillating Fifth Wheel Coupler	☒		
NOTES:							
FIFTH WHEEL BUSHINGS BAD - REPLACED FIFTH WHEEL PLAY - ADJUSTED							
The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #8662624) the inspection and a copy has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 21/2008 and the applicable Inspection Manual.							
Date of Inspection	2026/03/03	Technician Number	D1976	Facility Number	19938	Signature	
Customer Acknowledgment						Date (Year/Month/Day)	
I understand if a vehicle inspection identifies defects and repairs are required, once repaired, this vehicle and the Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on the ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.						2026/03/03	
						Customer Signature	

VSSRO/2016

P=PASS F=FAIL NA=Not Applicable

Page 4 of 4