



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	63500 kg	Brake Type:	Air
Owner Name:	MASI TRANSPORT LTD		
Address:	1924 GLENMOUNT DR SW		
City:	CALGARY	Province:	AB
		Postal Code:	T3E4B6
Telephone Number:	(403) 998-5112		
Vehicle Identification Number:	3HSDZAPR1NN286156		
Make:	International	Model:	LT625
Year:	2022	Unit Number:	417
Odometer:	644084 KM	Licence Plate Number:	0AX296
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
North Truck and Trailer Repair Ltd.	19938
Inspection Technician Name:	Technician Number:
Harman Dhillon	C6493
Inspection Technician Signature:	<i>HSD</i>
Inspection Date:	2026/01/08

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle Truck		Gross Vehicle Weight registered 63500 kg																																																																																																																			
Vehicle Information																																																																																																																					
VIN	3	H	S																																																																																																																		
D	Z	A	P																																																																																																																		
R	1	N	N																																																																																																																		
2	8	6	1																																																																																																																		
5	6																																																																																																																				
Unit Number 417	Year 2022	Make International	Model LT625																																																																																																																		
Registered Owner's Name MASI TRANSPORT LTD		Plate Number 0AX296																																																																																																																			
Address 1924 GLENMOUNT DR SW		Postal Code T3E4B6	Phone Number (403) 998-5112																																																																																																																		
Drum Brakes:		Disc Brakes: D-Full Inspection Wheel Removed																																																																																																																			
<table border="1"> <thead> <tr> <th colspan="2">LEFT</th> <th colspan="2">FRONT</th> <th colspan="2">RIGHT</th> </tr> </thead> <tbody> <tr> <td>100 psi</td> <td>43.15 mm</td> <td>Drums/Rotors</td> <td>43.76 mm</td> <td>100 psi</td> <td>43.76 mm</td> </tr> <tr> <td>12 mm</td> <td>12 mm</td> <td>Linings/Pads</td> <td>16 mm</td> <td>12 mm</td> <td>12 mm</td> </tr> <tr> <td></td> <td>N/A mm</td> <td>Push Rod Travel</td> <td>N/A mm</td> <td></td> <td>N/A mm</td> </tr> <tr> <td>100 psi</td> <td>42.87 mm</td> <td>Drums/Rotors</td> <td>42.97 mm</td> <td>100 psi</td> <td>42.97 mm</td> </tr> <tr> <td>12 mm</td> <td>13 mm</td> <td>Linings/Pads</td> <td>14 mm</td> <td>12 mm</td> <td>13 mm</td> </tr> <tr> <td></td> <td>N/A mm</td> <td>Push Rod Travel</td> <td>N/A mm</td> <td></td> <td>N/A mm</td> </tr> <tr> <td>100 psi</td> <td>42.72 mm</td> <td>Drums/Rotors</td> <td>42.90 mm</td> <td>100 psi</td> <td>42.90 mm</td> </tr> <tr> <td>12 mm</td> <td>11 mm</td> <td>Linings/Pads</td> <td>14 mm</td> <td>12 mm</td> <td>11 mm</td> </tr> <tr> <td></td> <td>N/A mm</td> <td>Push Rod Travel</td> <td>N/A mm</td> <td></td> <td>N/A mm</td> </tr> <tr> <td>psi</td> <td>mm</td> <td>Drums/Rotors</td> <td>mm</td> <td>psi</td> <td>mm</td> </tr> <tr> <td>mm</td> <td>mm</td> <td>Linings/Pads</td> <td>mm</td> <td>mm</td> <td>mm</td> </tr> <tr> <td></td> <td>mm</td> <td>Push Rod Travel</td> <td>mm</td> <td></td> <td>mm</td> </tr> <tr> <td>psi</td> <td>mm</td> <td>Drums/Rotors</td> <td>mm</td> <td>psi</td> <td>mm</td> </tr> <tr> <td>mm</td> <td>mm</td> <td>Linings/Pads</td> <td>mm</td> <td>mm</td> <td>mm</td> </tr> <tr> <td></td> <td>mm</td> <td>Push Rod Travel</td> <td>mm</td> <td></td> <td>mm</td> </tr> <tr> <td>psi</td> <td>mm</td> <td>Drums/Rotors</td> <td>mm</td> <td>psi</td> <td>mm</td> </tr> <tr> <td>mm</td> <td>mm</td> <td>Linings/Pads</td> <td>mm</td> <td>mm</td> <td>mm</td> </tr> <tr> <td></td> <td>mm</td> <td>Push Rod Travel</td> <td>mm</td> <td></td> <td>mm</td> </tr> </tbody> </table>				LEFT		FRONT		RIGHT		100 psi	43.15 mm	Drums/Rotors	43.76 mm	100 psi	43.76 mm	12 mm	12 mm	Linings/Pads	16 mm	12 mm	12 mm		N/A mm	Push Rod Travel	N/A mm		N/A mm	100 psi	42.87 mm	Drums/Rotors	42.97 mm	100 psi	42.97 mm	12 mm	13 mm	Linings/Pads	14 mm	12 mm	13 mm		N/A mm	Push Rod Travel	N/A mm		N/A mm	100 psi	42.72 mm	Drums/Rotors	42.90 mm	100 psi	42.90 mm	12 mm	11 mm	Linings/Pads	14 mm	12 mm	11 mm		N/A mm	Push Rod Travel	N/A mm		N/A mm	psi	mm	Drums/Rotors	mm	psi	mm	mm	mm	Linings/Pads	mm	mm	mm		mm	Push Rod Travel	mm		mm	psi	mm	Drums/Rotors	mm	psi	mm	mm	mm	Linings/Pads	mm	mm	mm		mm	Push Rod Travel	mm		mm	psi	mm	Drums/Rotors	mm	psi	mm	mm	mm	Linings/Pads	mm	mm	mm		mm	Push Rod Travel	mm		mm
LEFT		FRONT		RIGHT																																																																																																																	
100 psi	43.15 mm	Drums/Rotors	43.76 mm	100 psi	43.76 mm																																																																																																																
12 mm	12 mm	Linings/Pads	16 mm	12 mm	12 mm																																																																																																																
	N/A mm	Push Rod Travel	N/A mm		N/A mm																																																																																																																
100 psi	42.87 mm	Drums/Rotors	42.97 mm	100 psi	42.97 mm																																																																																																																
12 mm	13 mm	Linings/Pads	14 mm	12 mm	13 mm																																																																																																																
	N/A mm	Push Rod Travel	N/A mm		N/A mm																																																																																																																
100 psi	42.72 mm	Drums/Rotors	42.90 mm	100 psi	42.90 mm																																																																																																																
12 mm	11 mm	Linings/Pads	14 mm	12 mm	11 mm																																																																																																																
	N/A mm	Push Rod Travel	N/A mm		N/A mm																																																																																																																
psi	mm	Drums/Rotors	mm	psi	mm																																																																																																																
mm	mm	Linings/Pads	mm	mm	mm																																																																																																																
	mm	Push Rod Travel	mm		mm																																																																																																																
psi	mm	Drums/Rotors	mm	psi	mm																																																																																																																
mm	mm	Linings/Pads	mm	mm	mm																																																																																																																
	mm	Push Rod Travel	mm		mm																																																																																																																
psi	mm	Drums/Rotors	mm	psi	mm																																																																																																																
mm	mm	Linings/Pads	mm	mm	mm																																																																																																																
	mm	Push Rod Travel	mm		mm																																																																																																																
Park Brake Lining Left N/A mm Right N/A mm Trans N/A mm Wheel Torque Checked ☒ Inner N/A lbs Outer 500 lbs																																																																																																																					

VSSRO12018

P=PASS F=FAIL NA=Not Applicable

Page 1 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR

Section 1 - Power Train			
Component	P	F	NA
1.1 Accelerator Pedal/Throttle Actuator	☒		
1.2 Exhaust System	☒		
1.3 Emission Control Systems and Devices	☒		
1.4 Drive Shaft	☒		
1.5 Clutch and Clutch Pedal	☒		
1.6 Engine/Transmission Mount	☒		
1.7 Engine/Shaft Down	☒		
1.8 Engine Start Safety Feature	☒		
1.9 Gear Position Indicator	☒		
1.10 Engine or Accessory Drive Belt	☒		
1.11 Hybrid Electric Vehicle & Electric Vehicle Power Train System	☒		
1.12 Gasoline or Diesel Fuel System	☒		
1.13 Pressurized or Liquefied Fuel System (LPG, CNG, & LNG)	☒		
* SEE APPENDIX A *			
NOTES:			
APPENDIX "A"			
Component	P	F	NA
A.1 Liquefied Petroleum Gas (LPG or Propane) Fuel System	☒		
A.2 Compressed Natural Gas (CNG) Fuel System	☒		
A.3 Liquefied Natural Gas (LNG) Fuel System	☒		
NOTES:			
Section 2 - Suspension			
Component	P	F	NA
2.1 Suspension & Frame Attachments	☒		
2.2 Axle Attaching & Tracking Components	☒		
2.3 Axle & Axle Assembly	☒		
2.4 Spring & Spring Attachment	☒		
2.5 Air Suspension	☒		
2.6 Self-Steer and Controlled-Steer Axle	☒		
2.7 Shock Absorber/Strut Assembly	☒		
NOTES:			
Section 3H - Hydraulic Brakes			
Component	P	F	NA
3H.1 Hydraulic System Components	☒		
3H.2 Brake Pedal/Actuator	☒		
3H.3 Vacuum Assisted (Boost) System	☒		
3H.4 Hydraulic Assist (Boost) System	☒		
3H.5 Air Assist (Boost) System	☒		
3H.6 Air-Over-Hydraulic Brake System	☒		
3H.11 Brake System Indicator Lamps	☒		
3H.12 Drum Brake System Components	☒		
3H.13 Disc Brake System Components	☒		
3H.14 Mechanical Parking Brake	☒		
3H.15 Spring-Applied Air-Released Parking Brake	☒		
3H.16 Spring-Applied Hydraulic-Released Parking Brake	☒		
3H.17 Anti-Lock Brake System (ABS)	☒		
3H.18 Stability Control System	☒		
3H.19 Brake Performance	☒		
NOTES:			
Section 3A - Air Brakes			
Component	P	F	NA
3A.1 Air Compressor	☒		
3A.2 Air Supply System	☒		
3A.4 Air Tank	☒		
3A.5 Air Tank Check Valves	☒		
3A.6 Brake Pedal/Actuator	☒		
3A.7 Treadle Valve and Trailer Hand Valve	☒		
3A.8 Brake Valves & Controls	☒		
3A.9 Proportioning, Inversion or Modulation Valve	☒		
3A.10 Towing Vehicle (Tractor) Protection System	☒		
3A.13 Air System Components	☒		
3A.14 Brake Chamber	☒		
3A.15 Drum Brake System Components	☒		
3A.16 S-Cam Drum Brake System	☒		
3A.17 Brake Shoe Travel (Wedge Brakes)	☒		
3A.18 Disc Brake System Components	☒		
3A.19 Anti-Lock Brake System (ABS)	☒		
3A.21 Stability Control System	☒		
3A.23 Brake Performance	☒		
NOTES:			

VSSRO12018

P=PASS F=FAIL NA=Not Applicable

Page 2 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR

Section 3A - Air Brakes			
Component	P	F	NA
3A.11 Parking Brake & Emergency Application	☒		
NOTES:			
Section 4 - Steering			
Component	P	F	NA
4.1 Steering Control and Linkage	☒		
4.2 Power Steering System (Hydraulic and Electric)	☒		
4.3 Steering Operation (Active Steer Axle)	☒		
4.4 Kingpin	☒		
4.5 Self-Steer and Controlled-Steer Axle	☒		
NOTES:			
Section 5 - Instruments and Auxiliary Equipment			
Component	P	F	NA
5.1 Fire Extinguisher	☒		
5.2 Hazard Warning Kit	☒		
5.3 Horn	☒		
5.4 Speedometer	☒		
5.5 Odometer	☒		
5.6 Windshield Wiper/Washer	☒		
5.7 Heater & Windshield Defroster	☒		
5.8 Fuel-Burning Auxiliary Heater	☒		
5.9 Chain/Headache Rack	☒		
5.10 Auxiliary Controls and Devices	☒		
5.12 Auxiliary Drive Controls	☒		
NOTES: CITY HORN NOT WORKING - REPAIRED			
Section 6 - Lamps			
Component	P	F	NA
6.1 Required Lamps	☒		
6.2 Reflex Reflector	☒		
6.3 Retro-Reflective Marking	☒		
6.4 Instrument Panel Lamps	☒		
6.5 Headlamp Aim	☒		
NOTES:			
Section 7 - Electrical System			
Component	P	F	NA
7.1 Wiring	☒		
7.2 Battery	☒		
7.3 Trailer Cord (output to towed vehicle)	☒		
NOTES:			
Section 8 - Body			
Component	P	F	NA
8.1 Hood or Engine Enclosure	☒		
8.2 Tire Cab	☒		
8.3 Air-Suspended Cab	☒		
8.4 Cab and Passenger-Vehicle Body	☒		
8.5 Cargo Body	☒		
8.6 Frame, Rails & Mounts	☒		
8.7 Unified Body Elements	☒		
8.8 Cab or Cargo Door	☒		
8.9 Cargo Tank or Vessel	☒		
8.10 Body, Device or Equipment Attached or Mounted to the	☒		
8.11 Bumper	☒		
8.12 Windshield	☒		
8.13 Side Windows	☒		
8.14 Rear Window	☒		
8.15 Interior Sun Visor	☒		
8.16 Exterior Windshield Sun Visor	☒		
8.17 Rear-View Mirror	☒		
8.18 Seat	☒		
8.19 Seat Belt/Occupant Restraint	☒		
8.20 Fender/Mud Flap	☒		
NOTES:			

VSSRO12018

P=PASS F=FAIL NA=Not Applicable

Page 3 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR

Section 8 - Body			
Component	P	F	NA
8.1 Refrigeration/Heater Unit Fuel System (Refrigerator or Auxiliary Power Unit (APU))	☒		
8.24 Aerodynamic Device & Attachment	☒		
NOTES: LEFT SIDE CAB BUSHING WORN - REPLACED			
Section 9 - Tires and Wheels			
Component	P	F	NA
9.1 Tire Tread Depth	☒		
9.2 Tire Tread Condition	☒		
9.3 Tire Sidewall & Manufacturer Markings	☒		
9.4 Tire Inflation Pressure	☒		
9.5 Wheel Hub	☒		
9.6 Wheel Bearing	☒		
9.7 Wheel/Rim (Applies to all wheel types)	☒		
9.8 Multi-Piece Wheel/Rim	☒		
9.9 Spoke Wheel/Dismountable Rim System	☒		
9.10 Disc Wheel System	☒		
9.11 Wheel Fasteners (Nuts, Bolts and Studs)	☒		
NOTES: 1ST AXLE BOTH WHEEL SEALS LEAKING - REPLACED			
Section 10 - Couplers and Hitches			
Component	P	F	NA
10.1 Hitch Assembly, Structure & Attaching Components	☒		
10.2 Secondary Attachment (Safety Chain or Cable)	☒		
10.3 Pin/End Hook, Pin Hitch, or Coupler Hitch	☒		
10.4 Ball Type Hitch	☒		
10.5 Roll-Coupling Hitch	☒		
10.6 Automated Coupling Device	☒		
10.7 Fifth Wheel Coupler	☒		
10.8 Oscillating Fifth Wheel Coupler	☒		
NOTES: FIFTH WHEEL BUSHINGS WORN - REPLACED			
Certification			
The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #8493085) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.			
Date of Inspection 2026/01/08	Technician Number C6493	Facility Number 19938	Signature <i>ASD</i>
Customer Acknowledgment			Date (Year/Month/Day) 2026/01/08
I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			Customer Signature

VSSRO12018

P=PASS F=FAIL NA=Not Applicable

Page 4 of 4